
Vol. 5 of 5 EP-457/2013/C Central Kowloon Route Kai Tak East Contract No. HY/2018/02 July 2020







Environmental Permit No. EP-457/2013/C

Central Kowloon Route

Independent Environmental Checker Verification

| Reference Document/Plan | |
|--|---------------------------------------|
| Document/ Plan to be Certified / Verified: | Monthly EM&A Report No.11 (July 2020) |
| Date of Report: | 10 August 2020 (Rev. 2) |
| Date received by IEC: | 10 August 2020 |

Kai Tak East (HY/2018/02)

Reference EP Condition

Works Contract:

Environmental Permit Condition: 3.4

Submission of Monthly EM&A Report of the Project

3.4 Four hard copies and one electronic copy of monthly EM&A Report shall be submitted to the Director within 2 weeks after the end of each reporting month throughout the entire construction period. The EM&A Reports shall include a summary of all non-compliance. The submissions shall be certified by the ET Leader and verified by the IEC as complying with the requirements as set out in the EM&A Manual before submission to the Director. Additional copies of the submission shall be provided to the Director upon request by the Director.

IEC Verification

Mondy 20.

I hereby verify that the above referenced document/plan complies with the above referenced condition of EP-457/2013/C.

Ms Mandy To Date: 11 August 2020

Independent Environmental Checker

Our ref: 0436942_IEC Verification Cert_KTE_Monthly EM&A Rpt No.11.docx







Unit C, 11/F, Ford Glory Plaza, Nos. 37–39 Wing Hong Street, Cheung Sha Wan, Kowloon.

C

Tel. : (852) 2698 6833 Fax.: (852) 2698 9383

Alchmex – Paul Y Joint Venture

Central Kowloon Route Contract HY/2018/02 Section of Kai Tak East

Monthly EM&A Report No. 11

(Period from 1 to 31 July 2020)

Rev. 2

(10 Aug 2020)

| | | Name | Signature |
|--------------------------|---|--|-----------|
| Prepared by | | Philip Y. N. Chan (Assistant Environmental Consultant) | Philip |
| Checked Reviewed by | & | Nelson T. H. Tsui (Senior Environmental Consultant) | 74 |
| Approved Certified by | & | Kevin W. M. Li (Environmental Team Leader) | X: |

TABLE OF CONTENTS

EXECUTIVE SUMMARY

| 1. | BASIC PROJECT INFORMATION | (|
|----|---|--------------|
| 2. | ENVIRONMENTAL STATUS | 9 |
| 3. | MONITORING RESULTS | 10 |
| 4. | SUMMARY OF COMPLAINTS, NOTIFICATION OF SUMMONS AND PROSECUTIONS | 16 |
| 5. | EM&A SITE INSPECTION | 16 |
| 6. | FUTURE KEY ISSUES | 17 |
| 7. | CONCLUSION AND RECOMMENDATIONS | 18 |

LIST OF APPENDICES

- A. Alignment and Works Area for the Contract No. HY/2018/02
- B. Construction Programme
- C. Project Organization Chart
- D. Dust Event-Action Plan (EAP)
- E. Noise Event-Action Plan (EAP)
- F. Environmental Mitigation Implementation Schedule (EMIS)
- G. Monitoring Schedules of the Reporting Month
- H. Calibration Certificate (Air Monitoring)
- I. The Certification of Laboratory with HOKLAS Accredited Analytical Tests
- J. Location Plan of Air Quality Monitoring Station
- K. Monitoring Data (Air Monitoring)
- L. Waste Flow Table
- M. Statistics on Complaint, Notifications of Summons and Successful Prosecutions
- N. Monitoring Schedule of the Coming Month
- O. Interim Report for the Complaint

EXECUTIVE SUMMARY

- Alchmex Paul Y Joint Venture ("Contractor") commenced the construction works of **A.1** Highway Department (HyD) Central Kowloon Route Contract No. HY/2018/02 - Section of Kai Tak East ("The Project") on 9 September 2019. This is the 11th monthly Environmental Monitoring and Audit (EM&A) report presenting the EM&A works carried out during the period from 1 Jul 2020 to 31 Jul 2020.
- A.2 A summary of major Construction activities by Contractor for the Project during the reporting month is listed below.

Construction Activities undertaken

- Ground Investigation at Portion 2B & 3B & Kai Cheung U Turn & Kai Cheung Loop Road.
- Bored Pile at Portion 1A, 2B & 3B.
- Foundation Work for the Foot Bridge at Kai Fuk Road.
- Sheetpiling Works for Adit at Area 1D3.
- Sheetpiling Works for Underpass at Portion 3B.
- Construction of Marine Platform at Kai Tak Nallah.
- A.3 A summary of regular construction dust monitoring activities in this reporting period is listed below:

Construction dust (24-hour TSP) monitoring

E-A1 6 times, 1 voided sample, 5 valid

samples

Construction dust (1-hour TSP) monitoring

E-A1 15 times

- Due to the short-cirucited electricity supply for HVS equipment on 17 Jul 2020 at Hong A.4 Kong International Trade and Exhibition Centre (E-A1), 24-hour TSP dust monitoring was suspended. Immediate equipment inspection was performed and the problem was not fixed on 21 Jul 2020. A back-up HVS equipment was replaced on 22 Jul 2020 for the malfunctioned HVS equipment at E-A1. Supplementary 24-hour TSP dust monitoring was conducted on 22 Jul 2020.
- A.5 Joint weekly site inspections were conducted by representatives of Environmental team (ET), Contractor and Engineer on 2, 8, 15, 22 and 29 July 2020. Also, a joint site inspection with Independent Environmental Checker (IEC) was undertaken on 22 July 2020. Details of the audit findings and implementation status are presented in Section 5.
- Bi-weekly inspection of the implementation of landscape and visual mitigation measures by A.6 ET was conducted on 8 and 22 July 2020. Details of the audit findings and implementation status are presented in Section 5.
- A.7 Details of waste management are presented in Section 3.
- No exceedance of the Action and Limit Levels of 24-hour TSP and 1-hour TSP monitoring A.8

were recorded during the reporting month.

- A.9 One Action Level of construction noise was triggered during the reporting period as there was one documented complaint received on 1 Jul 2020 related to construction noise at BEM office.
- A.10 One noise-related complaint was received in the reporting month on 1 Jul 2020. After investigation by the senior environmental inspector from EPD and Contractor, precautionary measures have been proposed to the Contractor. The interim report for the complaint is shown in Appendix O.
- A.11 No notification of summons and prosecution was received in the reporting period.
- A.12 A summary of Construction Activities provided by Contractor in next reporting month is listed below:

Construction Activities to be undertaken

- Ground Investigation at Portion 2B & 3B & Kai Cheung U Turn & Kai Cheung Loop Road.
- Bored Pile at Portion 1A, 2B, 3B & Kai Cheung Loop Road.
- Foundation Work for the Foot Bridge at Kai Fuk Road.
- Sheetpiling Works for Adit at Area 1D3.
- Sheetpiling Works for Underpass at Portion 3B.
- Construction of Marine Platform at Kai Tak Nallah.

1. Basic Project Information

- 1.1. Central Kowloon Route (CKR) is a 4.7 km long dual 3-lane trunk road in Central Kowloon linking Yau Ma Tei Interchange in West Kowloon with the road network on Kai Tak Development and Kowloon Bay in East Kowloon.
- 1.2. The Central Kowloon Route Design and Construction Environmental Impact Assessment Report (Register No.: AEIAR-171/2013) was approved with conditions by the Environmental Protection Department (EPD) on 11 July 2013. An Environmental Permit (EP 457/2013) was issued on 9 August 2013. Variations of EP (VEP) was subsequently applied for and the latest EP (EP-457/2013/C) was issued by EPD on 16 January 2017.
- 1.3. The construction of the CKR had been divided into different sections. This Contract No. HY/2018/02 Section of Kai Tak East (KTE) covers part of the construction activities located at Kai Tak under the EP which includes:
 - Section of Kai Tak East
 - i. construction of an approximately 700m long dual 2-lane Central Kowloon Route mainline at Kai Tak, including at-grade roads and bridges;
 - ii. construction of Kai Tak Interchange, including bridges, underpass, and associated at-grade slip roads, connecting the Central Kowloon Route with the existing road network;
 - iii. construction of a footbridge, and demolition/backfill of an existing subway across Kai Fuk Road;
 - iv. realignment of existing Kai Fuk Road, Kai Cheung Road and Kai Cheung Road/Kai Fuk Road loop road;
 - v. reconstruction of an approximately 30m long existing multi-cell box culvert;
 - vi. construction of an approximately 130m long underground ventilation and E&M audit;
 - vii. construction of Ring Road Underpass, connecting Central Kowloon Route mainline and Central Kowloon Route Administration Building;
 - viii. junction improvement works at existing Wang Kwong Road/Kai Cheung Road and Wang Kwong Road/Lam Hing Street junctions;
 - ix. arrangement and implementation of cross boundary disposal of construction and demolition materials; and
 - x. associated roadworks, drainage, waterworks, landscaping works, geotechnical works, and electrical and mechanical works.

The alignment and works area for the Contract No. HY/2018/02 - are shown in Appendix A.

1.4. A summary of major construction activities provided by the Contractor in this reporting period is shown in Table 1.1. The construction programme is presented in Appendix B.

Table 1.1 Summary of Construction Activities provided by Contractor during this Reporting Month.

Construction Activities undertaken

- Ground Investigation at Portion 2B & 3B & Kai Cheung U Turn & Kai Cheung Loop Road.
- Bored Pile at Portion 1A, 2B & 3B.
- Foundation Work for the Foot Bridge at Kai Fuk Road.
- Sheetpiling Works for Adit at Area 1D3.
- Sheetpiling Works for Underpass at Portion 3B.
- Construction of Marine Platform at Kai Tak Nallah.
 - 1.5. The project organisational chart specifying management structure and contact details are shown in Appendix C.
 - 1.6. A summary of the valid permits, licences, and /or notifications on environmental protection for this Project is presented in Table 1.2

Table 1.2 Summary of the Status of Valid Environmental Licence, Notification, Permit and Documentations

| Permit/ Licences/ | Valid | Period | | | |
|-----------------------------|-------------|----------------|---------------|---|--|
| Notification | From | То | Status | Remark | |
| /Reference No. | Tiom | 10 | | | |
| Environmental Permit | Γ | , | | 1 | |
| EP-457/2013/C | 23 Apr 2019 | End of Project | Valid | - | |
| Wastewater Discharge Li | | , | | 1 | |
| WT00035029-2019 | 17 Dec 2019 | 31 Dec 2024 | Valid | <u> </u> | |
| Notification of Constructi | | | | ion Dust) Regulation | |
| 445001 | Apr 2019 | Dec 2023 | Notified | - | |
| Chemical Waste Produce | | E 1 (D : / | X7 1' 1 | | |
| WPN5113-247-A2940-01 | 17 May 2019 | End of Project | Valid | - | |
| Billing Account for Dispo | | | Val: d | 1 | |
| 7034073 | 15 Jun 2019 | End of Project | Valid | - | |
| Construction Noise Perm | | | | 1 | |
| GW-RE0298-20 | 5-May-20 | 5-Aug-20 | Superseded by | | |
| | | | GW-RE0398-20 | Central Divider Removal | |
| GW-RE0398-20 | 21-May-20 | 18-Aug-20 | Valid | | |
| GW-RE0160-20 | 16-Mar-20 | 15-Sep-20 | Superseded by | | |
| | | | GW-RE0415-20 | General Work for Area A | |
| GW-RE0415-20 | 29-May-20 | 15-Sep-20 | Valid | | |
| CW DE0007 20 | 24 E-1- 20 | 11 4 20 | Superseded by | | |
| GW-RE0097-20 | 24-Feb-20 | 11-Aug-20 | GW-RE0321-20 | General Work for Area B and Site Office | |
| GW-RE0321-20 | 6-May-20 | 28-Oct-20 | Valid | und Site Office | |
| GW-RE0299-20 | 5 May 20 | 4-Jul-20 | Superseded by | | |
| OW-KE0299-20 | 5-May-20 | 4-301-20 | GW-RE0551-20 | Kai Cheung U Turns | |
| GW-RE0551-20 | 4-Jul-20 | 3-Jan-21 | Valid | | |
| GW-RE0411-20 | 26-May-20 | 25-Jul-20 | Expired | Portion 2B | |
| GW-RE0600-20 | 26-Jul-20 | 25-Nov-20 | Valid | | |
| GW-RE0352-20 | 16-May-20 | 9-Aug-20 | Valid | Temporary Decking at Kai Fuk Road | |
| GW-RE0511-20 | 16-Jun-20 | 10-Aug-20 | Valid | Watermain Diversion | |
| GW-RE0528-20 | 27-Jun-20 | 26-Sep-20 | Valid | BEM Office | |
| GW-RE0608-20 | 27-Jul-20 | 29-Aug-20 | Valid | Street Light Relocation | |
| GW-RE0620-20 | 28-Jul-20 | 29-Aug-20 | Valid | High Mast CCTV | |
| GW-RE0632-20 | 31-Jul-20 | 29-Aug-20 | Valid | Road Paving at Kai Fuk Road | |

2. ENVIRONMENTAL STATUS

2.1. Environmental permit (EP) conditions under the EIAO, submission status under the EP and implementation status of mitigation measures had been reviewed and implemented on schedule. The status of required submissions under the EP (EP-457/2013/C) as of the reporting period for the Project are summarised in Table 2.1

Table 2.1 Summary of Status of Required Submission for EP-457/2013/C for the Project

| EP Condition (EP-457/2013/C) | Submission | Submission date | |
|---------------------------------|--------------------------------------|-----------------|--|
| Condition 1.12 | Notification of Commencement Date of | 26 Jul 2019 | |
| Condition 1.12 | Construction of the Project | 20 Jul 2019 | |
| Condition 2.4 | Management organisation of the main | 26 Jul 2019 | |
| Collation 2.4 | construction companies | 20 Jul 2019 | |
| Condition 2.5 | Construction Programme and EP | 26 Jul 2019 | |
| Collation 2.3 | Submission Schedule | 20 Jul 2019 | |
| Condition 2.6 | Design Drawing | 26 Jul 2019 | |
| Condition 2.8 | Landscape Mitigation Plan | 26 Jul 2019 | |
| Condition 3.3 | Baseline Monitoring Report | 21 Aug 2019 | |
| Condition 3.4 | Monthly EM&A Report (June 2020) | 14 Jul 2020 | |

2.2. Details of the major construction activities provided by the Contractor in this reporting period are shown in Table 2.2.

Table 2.2 Summary of Construction Activities provided by Contractor during the Reporting Month.

Construction Activities undertaken

- Ground Investigation at Portion 2B & 3B & Kai Cheung U Turn & Kai Cheung Loop Road.
- Bored Pile at Portion 1A, 2B & 3B.
- Foundation Work for the Foot Bridge at Kai Fuk Road.
- Sheetpiling Works for Adit at Area 1D3.
- Sheetpiling Works for Underpass at Portion 3B.
- Construction of Marine Platform at Kai Tak Nallah.
 - 2.3. The drawing showing the the project layout and the location of the monitoring station and environmental sensitive receivers are attached in Appendix A and Appendix J. Co-ordinates of the monitoring location is shown in below:

Table 2.3 Summary for the location of monitoring station

| Monitoring Location | Location ID | Latitude | Longitude |
|---|-------------|-----------|------------|
| Hong Kong International Trade and Exhibition Centre | E-A1 | 22.323912 | 114.203512 |

3. MONITORING RESULTS

3.1. Monitoring Parameters

Air Quality

- 3.1.1. The impact monitoring had been carried out in accordance with section 5.8 of the approved EM&A Manual to determine the 1-hour and 24-hour total suspended particulates (TSP) levels at the monitoring locations in the reporting month.
- 3.1.2. The sampling frequency of at least once in every 6 days, shall be strictly observed at the monitoring stations for 24-hour TSP monitoring. For 1-hour TSP monitoring, the sampling frequency of at least 3 times in every 6 days should be undertaken when the highest dust impact occurs.
- 3.1.3. General meteorological conditions (wind speed, direction and precipitation) and notes regarding any significant adjacent dust producing sources had also been recorded throughout the impact monitoring period.
- 3.2. Monitoring Equipment

Air Quality

- 3.2.1. 1-hour TSP levels and 24-hour TSP had been measured with direct reading dust meter and High Volume Samplers respectively. It has been demonstrated its capability in achieving comparable results with high volume sampling method as set out in the Title 40 of the Code of Federal Regulations, Chapter 1 (Part 50).
- 3.2.2. The 1-hour TSP meter was calibrated by the manufacturer prior to purchasing. Zero response of the instrument was checked before and after each monitoring event. Operation of the 1-hour TSP meter followed manufacturer's Operation and Service Manual. The 24-hour TSP meter was calibrated against firmware 80570-8100-V1.0.4, annually. Operation of the 24-hour TSP meter followed manufacturer's Operation and Service Manual. Valid calibration certificate of dust monitoring equipment is attached in Appendix H.
- 3.2.3. A summary of the equipment that was deployed for the 24- hour averaged monitoring is shown in Table 3.1. The TSP monitoring was conducted as per the schedule presented in Appendix G.
- 3.2.4. The equipment used for 1-hour TSP and 24-hour TSP measurement and calibration are summarised in Table 3.1

| Monitoring Parameter | Monitoring Equipment | Serial Number | Date of Calibration |
|----------------------|------------------------------|---------------|---------------------|
| 1-hour TSP | LD-5R Digital Dust Indicator | 851820 | 23 Aug 2019 |
| 24-hour TSP | TE-5170X High Volume | 1085 | 26 Jun, 11 Jul 2020 |
| | Sampler | | |
| | TE-5170X High Volume | 1049 | 22 Jul 2020 |
| | Sampler | | |
| | TE-5028A Calibration Kit | 3702 | 10 Oct 2019 |

Table 3.1 Construction Dust Monitoring Equipment

3.3. Monitoring Methodology and QA/QC results

Air Quality

- 3.3.1. The 1-hour TSP monitor, portable dust meters (Sibata Digital Dust Indicator Model LD-5R) was used for the impact monitoring. The 1-hour TSP meters provides a real time 1-hour TSP measurement based on 90° light scattering. Three 1-hour TSP level were logged per every six days.
- 3.3.2. The 24-hour TSP monitor, High Volume Samplers (Tisch TE-5170x High Volume Air Sampler) were used for the impact monitoring. The 24-hour TSP monitoring consists of the following:
 - ◆ The HVS was set at the monitoring location, with electricity supply connected and secured;
 - ♦ HVS was calibrated before commencing the 1st measurement;
 - ◆ The filter paper was weight and provided by HOKLAS lab (Acumen Laboratory and Testing Limited and ALS Technichem (HK) Pty Ltd) before and after the sampling. Certificate of HOKLAS accredited laboratory can be referred to Appendix I;
 - ◆ The airflow over time during sampling process was recorded by the HVS.
- 3.3.3. HVSs were free-standing with no obstruction. The following criteria were considered in the installation of the HVS:
 - ◆ Appropriate support to secure the samples against gusty wind needed to be provided the monitoring station;
 - ◆ A minimum of 2m separation from walls, parapets and penthouses was required for rooftop samplers;
 - ◆ No furnace or incinerator flues was nearby;
 - ◆ Airflow around the sampler was unrestricted; and
 - Permission could be obtained to set up the samplers and gain access to the monitoring station
 - ◆ Any wire fence and gate, to protect the sampler, should not cause any obstruction during monitoring
 - ◆ A secured supply of electricity is needed to operate the samplers.

3.3.4. Preparation of Filter Papers

• Glass fiber filters were labelled and sufficient filters that were clean and without pinholes were selected;

- ◆ All filters were equilibrated in the conditioning environment for 24 hours before weighing. The conditioning environment temperature was around 25°C and not varied by more than ±3°C; the relative humidity (RH)was 40%; and
- ◆ Acumen Laboratory and Testing Limited and ALS Technichem (HK) Pty Limited, as HOKLAS accredited laboratory, implemented comprehensive quality assurance and quality control programmes on the filters.

3.3.5. Field Monitoring

- The power supply was checked to ensure that the HVS was working properly;
- ◆ The filter holder and area surrounding the filter were cleaned;
- ◆ The filter holder was removed by loosening the foul bolts and a new filter, with stamped number upward, on a supporting screen was aligned carefully;
- ◆ The filter was properly aligned on the screen so that the gasket formed an airtight seal on the outer edges of the filter;
- ◆ The swing bolts were fastened to hold the filter holder down to the frame. The pressure applied should be sufficient to avoid air leakage at the edges;
- The shelter lid was closed and secured with an aluminum strip;
- ◆ The HVS was warmed- up for about 5 minutes to establish run- temperature conditions;
- ◆ A new flow rate record sheet was inserted into the flow recorder;
- ◆ The flow rates of the HVS was checked and adjusted to between 1.22-1.37 ^{m³min-³}, which was within the range specified in the EM&A Manual (i.e. 0.6- 1.7 ^{m³min-³});
- ◆ The programmable timer was set for a sampling period of 24 hours ±hour, and the starting time, weather condition and filter number were recorded;
- ◆ The initial elapsed time was recorded;
- ◆ At the end of sampling, the sampled filter was removed carefully and folded in half so that only surfaces with collected particulate matter were in contact;
- ◆ The filter paper was placed in a clean plastic envelope and sealed; all monitoring information was recorded on a standard data sheet and
- ◆ The filters were sent to (Acumen Laboratory and Testing Ltd and ALS Technichem (HK) Pty Ltd) for analysis.

3.3.6. Maintenance and Calibration

- ◆ The HVS and their accessories were maintained in a good working condition. For example, motor brushes were replaced routinely and electrical wiring was checked to ensure a continuous power supply; and
- ◆ The flow rate of each HVS with mass flow controller was calibrated using an orifice calibrator, Initial calibrations of the dust monitoring equipment were conducted upon installation and prior to commissioning. Five- point calibration was carried out for HVS using TE-5028A Calibration Kit. HVS is calibrated in fortnightly Intervals. The calibration records for the HVS is given in Appendix H.

3.3.7. Wind Data Monitoring

◆ The wind speed has been recorded from Hong Kong Observatory- King's Park meteorological station, along with portable wind speed meter stand by as back up if malfunction occurred or data was not recorded from HKO

3.4. Monitoring Locations

Air Quality

3.4.1. During the site visit, air monitoring station Hong Kong International Trade and Exhibition Centre had been recommended in the approved EM&A Manual and approved by IEC. A designated air monitoring location was identified and agreed with IEC and EPD. Detail of the air monitoring station is described in Table 3.2. The location plan of air quality monitoring stations is shown in Appendix J.

Table 3.2 Location of the Dust Monitoring Stations

| Air Quality Monitoring Station | Dust Monitoring Station | |
|--------------------------------|--|--|
| E-A1 | Hong Kong International Trade and Exhibition | |
| | Centre | |

- 3.5. Monitoring date, time, frequency and duration
- 3.5.1. A summary of impact monitoring duration, sampling parameter and frequency is presented in Table 3.3.

Table 3.3: Summary of Impact Monitoring Programme

| Impact Monitoring | Duration | Sampling Parameter | Frequency |
|----------------------|----------------------------------|--------------------|----------------------|
| Dust | 1-hour continuous measurement | 1-hour TSP | 3 times per six days |
| Dust | 24-hour continuous sampling | 24-hour TSP | Once per six days |

3.6. Result Summary

Air Quality

3.6.1. According to our field observations, the major dust source identified at the designated air quality monitoring station in the reporting month are summarised in Table 3.4

Table 3.4 Observation at Dust Monitoring Station

| Monitoring Station | Major Dust Source |
|--------------------|-------------------|
| E-A1 | Nearby traffic |

3.6.2. Air quality impact monitoring for the reporting month was carried out on 6, 11, 17, 23 and 29 Jul 2020 at E-A1.

- 3.6.3. Due to the short-cirucited electricity supply for HVS equipment on 17 Jul 2020 at Hong Kong International Trade and Exhibition Centre (E-A1), 24-hour TSP dust monitoring was suspended.
- 3.6.4. Immediate equipment inspection was performed and the problem was not fixed on 21 Jul 2020. A back-up HVS equipment was replaced on 22 Jul 2020 for the malfunctioned HVS equipment at E-A1. Supplementary 24-hour TSP dust monitoring was conducted on 22 Jul 2020.
- 3.6.5. Scheduled monitoring for 1-hour TSP remained unaffected, only the schedule of 24-hour TSP was affected.
- 3.6.6. The results for 1-hour TSP and 24-hour TSP are summarized in Table 3.5 and Table 3.6. The measurement data and details of influencing factors such as weather conditions and site observation are presented in Appendix K.

Table 3.5 Summary of 1-hour TSP Monitoring Results

| Monitoring Location | Range(μg/m³) | Action Level(μg/m³) | Limit Level(µg/m³) |
|----------------------------|--------------|---------------------|--------------------|
| E-A1 | 31 - 53 | 279 | 500 |

Table 3.6 Summary of 24-hour TSP Monitoring Results

| Monitoring Location | Range(μg/m³) | Action Level(μg/m³) | Limit Level(μg/m³) |
|----------------------------|--------------|---------------------|--------------------|
| E-A1 | 21 - 32 | 142 | 260 |

Waste management

3.6.7. The waste generated from this Project includes inert C&D materials, and non-inert C&D materials. Non-inert C&D materials are made up of general refuse, vegetative wastes and recyclable wastes such as plastics and paper/cardboard packaging waste. Steel materials generated from the project are also grouped into non-inert C&D materials as the materials were not disposed of with other inert C&D materials. With reference to relevant handling records and trip tickets of this Project, the quantities of different types of waste generated in the reporting month are summarised in Table 3.7. Details of cumulative waste management data are presented as a waste flow table in Appendix L.

Table 3.7 Quantities of waste generated from the Project

| | Quantity | | | | | | |
|------------------|--------------|-------------|-------------------------|--------------------|--------------|--------------|--|
| Reporting period | | Chemical | Non-inert C&D Materials | | | | |
| | | | Others, | Recycled materials | | | |
| | | | e.g. | | | | |
| | Inert C&D | | General | | | | |
| | Materials | Waste | Refuse | | | | |
| | (in 'tonnes) | (in'000 Kg) | disposed | | | | |
| | | | at | Paper/card board | Plastics | Metals | |
| | | | Landfill | (in '000 Kg) | (in '000 Kg) | (in '000 Kg) | |
| | | | (in | | | | |
| | | | 'tonnes) | | | | |
| Jul-2020 | 11666.0 | 0.0 | 37.4 | 0.1 | 0.0 | 0.0 | |

4. SUMMARY OF COMPLAINTS, NOTIFICATION OF SUMMONS AND PROSECUTIONS

4.1. The Environmental Complaint Handling Procedure is shown in below Table 4.1:

Table 4.1 Environmental Complaint Handling Procedure

| Complaint Received via | Project Hotline | Complaint Received via 1823 or from or | ther | | |
|--|---|---|------|--|--|
| | | government departments | | | |
| | | | | | |
| Contractor notify ER, ET and IEC | | ER notify Contractor, ET and IEC | | | |
| | | | | | |
| Contractor log complain | nt and date of receipt ont | o the complaint database. Contractor, ER and ET | to | | |
| | conduct investig | gation of complaint | | | |
| | | | | | |
| If complaint is considered not valid | | If complaint is found valid | | | |
| | | | | | |
| ET or ER to reply the complainant if necessary | | Contractor to identify and implement remedial | | | |
| | | measures in consultation with the IEC, ET | and | | |
| | | ER. | | | |
| | | | | | |
| | | The ER, ET and IEC to review the effectiver | ness | | |
| | | of the Contractor's remedial measures and the updated situation; ET to undertake additional monitoring and audit to verify the situation if | | | |
| | | | | | |
| | | | | | |
| | necessary, and oversee that circumstances | | | | |
| | | to the complaint do not recur. ER to conduct | | | |
| | | further inspection as necessary. | | | |
| | | | | | |
| If the complaint is refer | red by the EPD, the Con | tractor to prepare interim report on the status of t | he | | |
| complaint investigation | and follow-up actions st | ipulated above, including the details of the remed | lial | | |
| measures and additiona | al monitoring identified | or already taken, for submission to EPD within th | ie | | |
| | time frame ass | igned by the EPD | | | |
| | | | | | |
| The ET to record the deta | ails of the complaint, res | ults of the investigation, subsequent actions taken | n to | | |

address the complaint and updated situation including the effectiveness of the remedial measures, supported by regular and additional monitoring results in the monthly EM&A reports

- 4.2. Should non-compliance of the criteria occur, action in accordance with the Action Plan in Appendix D and Appendix E shall be carried out.
- 4.3. No exceedance of the Action and Limit Levels of 24-hour TSP and 1-hour TSP monitoring was recorded during the reporting month.
- 4.4. One Action level of construction noise was triggered during the reporting period as there was one documented complaint received on 1 Jul 2020 related to construction noise at BEM office.
- 4.5. One noise-related complaint was received in the reporting month on 1 Jul 2020. After investigation by the senior environmental inspector from EPD and Contractor, precautionary measures have been proposed to the Contractor. The interim report for the complaint is shown in Appendix O.
- 4.6. No notification of summons and successful prosecution was received in the reporting period.
- 4.7. Statistics on complaints, notifications of summons and successful prosecutions are summarized in Appendix M.

5. EM&A SITE INSPECTION

- 5.1. Site inspections were carried out on a weekly basis to monitor the implementation of proper environmental pollution control and mitigation measures under the Contract. In the reporting period, 5 site inspections were carried out by the representative of ET, Contractor and Engineer on 2, 8, 15, 22 and 29 Jul 2020, along with bi-weekly inspection of the implementation of landscape and visual mitigation measures conducted on 8 and 22 Jul 2020.
- 5.2. One joint site inspection with IEC also undertaken on 22 Jul 2020. Minor deficiencies were observed during weekly site inspection. Key observations during the site inspections are summarized in Table 5.1.

Follow-up Status **Environmental Observations Date** 1. Drip tray was found broken at Portion 3B. 1. Broken drip tray was replaced by 2. Drip tray should be plugged at Portion 3B. new drip tray. 2 Jul 2020 3. Oil residue was found at Portion 3B. 2. Drip tray was plugged. 3. Oil residue was removed. 1. Hydraulic breaker should be placed on 1. The hydraulic breaker was tarpaulin sheet to prevent oil leakage in removed. 8 Jul 2020 KITEC. 2. Oil residue was removed. 2. Oil residue was found at Portion 2B. 1. Water spraying should be provided in KITEC. Watering was provided. 15 Jul 2020 2. Drip tray should be plugged at Portion 2B. Drip tray was plugged. 3. Oil leakage was found at Portion 2B. Oil stain was removed. 1. Water spraying should be enhanced at Portion Watering was provided. 22 Jul 2020 3B. 29 Jul 2020 Oil residue was removed. Oil residue was found at Portion 2B

Table 5.1 Site Observations

- 5.3. The Contractor had rectified all observation identified during environmental site inspection in the reporting period.
- 5.4. According to the EIA Study Report, Environmental Permit, contract documents and EM&A Manual, the mitigation measures detailed in the documents had been implemented as much as practical during the reporting period. An updated Implementation Status of Environmental Mitigation Measures (EMIS) is provided in Appendix F.

6. FUTURE KEY ISSUES


- 6.1. The construction activities provided by Contractor in the next reporting month are:
 - Ground Investigation at Portion 2B & 3B & Kai Cheung U Turn & Kai Cheung Loop Road.
 - Bored Pile at Portion 1A, 2B, 3B & Kai Cheung Loop Road.
 - Foundation Work for the Foot Bridge at Kai Fuk Road.
 - Sheetpiling Works for Adit at Area 1D3.
 - Sheetpiling Works for Underpass at Portion 3B.
 - Construction of Marine Platform at Kai Tak Nallah.
- 6.2. Potential environmental impacts arising from the above construction activities are mainly associated with dust and waste management.
- 6.3. The tentative schedule of 1-hour TSP and 24-hour TSP monitoring in the next reporting period is presented in Appendix N.
- 6.4. The construction programme for the Project for the next reporting month is presented in Appendix B.

7. CONCLUSION AND RECOMMENDATIONS

- 7.1. This 11th monthly EM&A Report presents the EM&A works undertaken during the period from 1 Jul 2020 to 31 Jul 2020 in accordance with the EM&A Manual and the requirement under EP- 457/2013/C.
- 7.2. Air quality (including 1-hour TSP and 24-hour TSP) was carried out in the reporting period. No exceedance of the Action and Limit Level was recorded for air quality impact monitoring during the reporting month. One Action Level of construction noise was triggered during the reporting period as there was one documented complaints received on 1 Jul 2020 related to construction noise at BEM office.
- 7.3. Due to the short-cirucited electricity supply for HVS equipment on 17 Jul 2020 at Hong Kong International Trade and Exhibition Centre (E-A1), 24-hour TSP dust monitoring was suspended. Immediate equipment inspection was performed and the problem was not fixed on 21 Jul 2020. A back-up HVS equipment was replaced on 22 Jul 2020 for the malfunctioned HVS equipment at E-A1. Supplementary 24-hour TSP dust monitoring was conducted on 22 Jul 2020.
- 7.4. Scheduled monitoring for 1-hour TSP remained unaffected, only the schedule of 24-hour TSP was affected.
- 7.5. Weekly environmental site inspections by the representative of ET, Contractor and Engineer were conducted during the reporting period. Joint site inspection with IEC were carried out on 22 Jul 2020. Minor deficiency was observed during site inspection and was rectified within the specified deadlines. The environmental performance of the Project was therefore considered satisfactory.
- 7.6. One noise-related complaint was received in the reporting month on 1 Jul 2020. After investigation by the senior environmental inspector from EPD and Contractor, precautionary measures have been proposed to the Contractor. The interim report for the complaint is shown in Appendix O.
- 7.7. No notification of summons or prosecution was received since commencement of the Contract.
- 7.8. The ET will keep track on the construction works to confirm compliance of environmental requirements and the proper implementation of all necessary mitigation measures.





Appendix A
Alignment and Works Area for the Contract No.
HY/2018/02








Appendix B
Construction Programme















































Appendix C Project Organization Chart





Appendix D

Dust Event-Action Plan (EAP)

| EVENT | ACTION | | | |
|--|---|--|--|---|
| EVENI | ET | IEC | ER | CONTRACTOR |
| ACTION LEV | EL | | | |
| 1.Exceedance for one sample | Identify source, investigate the causes of exceedance and propose remedial measures; Inform IEC and ER; Repeat measurement to confirm finding; Increase monitoring frequency to daily. | Check monitoring data submitted by ET; Check Contractor's working method. | 1. Notify Contractor. | Rectify any unacceptable practice; Amend working methods if appropriate. |
| 2.Exceedance for two or more consecutive samples | Identify source; Inform IEC and ER; Advise the ER on the effectiveness of the proposed remedial measures; Repeat measurements to confirm findings; Increase monitoring frequency to daily; Discuss with IEC and Contractor on remedial actions required; If exceedance continues, arrange meeting with IEC and ER; If exceedance stops, cease additional monitoring. | Check monitoring data submitted by ET; Check Contractor's working method; Discuss with ET and Contractor on possible remedial measures; Advise the ET on the effectiveness of the proposed remedial measures; Supervise Implementation of remedial measures. | Confirm receipt of notification of failure in writing; Notify Contractor; Ensure remedial measures properly implemented. | Submit proposals for remedial to ER within 3 working days of notification; Implement the agreed proposals; Amend proposal if appropriate. |
| LIMIT LEVEL | | | | |
| 1.Exceedance for one sample | Identify source, investigate the causes of exceedance and propose remedial measures; Inform ER, Contractor and | Check monitoring data submitted by ET; Check Contractor's working method; | Confirm receipt of notification of failure in writing; Notify Contractor; | Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC |

| EVENT | ACTION | | | |
|--|--|---|---|--|
| EVENI | ET | IEC | ER | CONTRACTOR |
| | EPD; 3. Repeat measurement to confirm finding; 4. Increase monitoring frequency to daily; 5. Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results. | 3. Discuss with ET and Contractor on possible remedial measures; 4. Advise the ER on the effectiveness of the proposed remedial measures; 5. Supervise implementation of remedial measures. | 3. Ensure remedial measures properly implemented. | within 3 working days of notification; Implement the agreed proposals; 4. Amend proposal if appropriate. |
| 2.Exceedance for two or more consecutive samples | Notify IEC, ER, Contractor and EPD; Identify source; Repeat measurement to confirm findings; Increase monitoring frequency to daily; Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented; Arrange meeting with IEC and ER to discuss the remedial actions to be taken; Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results; If exceedance stops, cease additional monitoring. | Discuss amongst ER, ET, and Contractor on the potential remedial actions; Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly; Supervise the implementation of remedial measures. | Confirm receipt of notification of failure in writing; Notify Contractor; In consultation with the IEC, agree with the Contractor on the remedial measures to be implemented; Ensure remedial measures properly implemented; If exceedance continues, consider what portion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is abated. | Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC within 3 working days of notification; Implement the agreed proposals; Resubmit proposals if problem still not under control; Stop the relevant portion of works as determined by the ER until the exceedance is abated. |

Note:

ET – Environmental Team

ER – Engineer's Representative

IEC – Independent Environmental Checker



Appendix E Noise Event-Action Plan (EAP)

| EVENT | | ACTIO | ON | |
|-----------------|--|--|--|--|
| | ET | IEC | ER | CONTRACTOR |
| Action Level | Identify source, investigate the causes of exceedance and propose remedial measures; Notify IEC and Contractor; Report the results of investigation to the IEC, ER and Contractor; Discuss with the Contractor and formulate remedial measures; Increase monitoring frequency to check mitigation effectiveness. | Review the analysed results submitted by the ET; Review the proposed remedial measures by the Contractor and advise the ER accordingly; Supervise the implementation of remedial measures. | Confirm receipt of notification of failure in writing; Notify Contractor; Require Contractor to propose remedial measures for the analysed noise problem; Ensure remedial measures are properly implemented | Submit noise mitigation proposals to IEC; Implement noise mitigation proposals. |

Note:

ET – Environmental Team

IEC – Independent Environmental Checker

ER – Engineer's Representative



Appendix F
Environmental Mitigation Implementation
Schedule (EMIS)

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|--|--|-------------------------|------------------------|-------------------------|---|--|
| | | | Constru | ction Dust Impact | | | | |
| S4.3.10 | D1 | The contractor shall follow the procedures and requirements given in the Air Pollution Control (Construction Dust) Regulation | Minimize dust impact at the nearby sensitive receivers | Contractor | All construction sites | Construction stage | APCO To control the dust impact To meet HKAQO and TM-EIA criteria | Implemented |
| \$4.3.10 | D2 | Mitigation measures in form of regular watering under a good site practice should be adopted. Watering once per hour on exposed worksites and haul road should be conducted to achieve dust removal efficiencies of 91.7%. While the above watering frequencies are to be followed, the extent of watering may vary depending on actual site conditions but should be sufficient to maintain an equivalent intensity of no less than 1.3 L/m² to achieve the dust removal efficiency. | Minimize dust impact at the nearby sensitive receivers | Contractor | All construction sites | Construction stage | APCO To control the dust impact To meet HKAQO and TM-EIA criteria | Implemented |
| \$4.3.10 | D3 | Proper watering at exposed spoil should be undertaken throughout the construction phase; Any excavated or stockpile of dusty material should be covered entirely by impervious sheeting or sprayed with water to maintain the entire surface wet and then removed or backfilled or reinstated where practicable within 24 hours of the excavation or unloading; Any dusty materials remaining after a stockpile is removed should be wetted with water and cleared from the surface of roads; A stockpile of dusty material should not be | Minimize dust impact at the nearby sensitive receivers | Contractor | All construction sites | Construction stage | APCO To control the dust impact To meet HKAQO and TM-EIA criteria | Implemented and rectified after observation. |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|---|--|-------------------------|----------------------|-------------------------|--|--------------------------|
| | | extended beyond the pedestrian barriers, fencing or traffic cones; The load of dusty materials on a vehicle leaving a construction site should be covered entirely by impervious sheeting to ensure that the dusty materials do not leak from the vehicle. Where practicable, vehicle washing facilities with high pressure water jet should be provided at every discernible or designated vehicle exit point. The area where vehicle washing takes place and the road section between the washing facilities and the exit point should be paved with concrete, bituminous materials or hardcores; When there are open excavation and reinstatement works, hoarding of not less than 2.4m high should be provided and properly maintained as far as practicable along the site boundary with provision for public crossing. Good site practice shall also be adopted by the Contractor to ensure the conditions of the hoardings are properly maintained throughout the construction period; The portion of any road leading only to construction site that is within 30m of a vehicle entrance or exit should be kept clear of dusty materials; Surfaces where any pneumatic or power-driven drilling, cutting, polishing or other mechanical breaking operation takes place should be sprayed with water or a dust suppression chemical | | | | | | |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|---|--|-------------------------|--|-------------------------|--|--------------------------|
| | | continuously; Any area that involves demolition activities should be sprayed with water or a dust suppression chemical immediately prior to, during and immediately after the activities so as to maintain the entire surface wet; Any skip hoist for material transport should be totally enclosed by impervious sheeting; Every stock of more than 20 bags of cement or dry-pulverised fuel ash (PFA) should be covered entirely by impervious sheeting or placed in an area sheltered on the top and the 3 sides; Loading, unloading, transfer, handling or storage of bulk cement or dry PFA should be carried out in a totally enclosed system or facility, and any vent or exhaust should be fitted with an effective fabric filter or equivalent air pollution control system Exposed earth should be properly treated by compaction, turfing, hydroseeding, vegetation planting or sealing with latex, vinyl, bitumen, shotcrete or other suitable surface stabilizer within six months after the last construction activity on the construction site or part of the construction site where the exposed earth lies. | | | | | | |
| S4.3.10 | | Implement regular dust monitoring under EM&A programme during the construction stage. | Monitoring of dust impact | Contractor | Selected rep. dust monitoring station | Construction stage | • TM-EIA | Implemented |

Construction Noise (Airborn

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|---|--|-------------------------|--|-------------------------|--|--------------------------|
| S5.4.1 | N1 | Implement the following good site practices: Only well-maintained plant should be operated on-site and plant should be serviced regularly during the construction programme; Machines and plant (such as trucks, cranes) that may be in intermittent use should be shut down between work periods or should be throttled down to a minimum; Plant known to emit noise strongly in one direction, where possible, be orientated so that the noise is directed away from nearby NSRs; Silencers or mufflers on construction equipment should be properly fitted and maintained during the construction works; Mobile plant should be sited as far away from NSRs as possible and practicable; Material stockpiles, mobile container site office and other structures should be effectively utilized, where practicable, to screen noise from on-site construction activities. | Control construction airborne noise | Contractor | All construction sites | Construction stage | • Annex 5, TM-EIAO | • Implemented |
| \$5.4.1 | N2 | Install temporary hoarding located on the site boundaries between noisy construction activities and NSRs. The conditions of hoardings shall be properly maintained throughout the construction period. | Reduce the construction noise levels at low-level zone of NSRs through partial screening | Contractor | All construction sites | Construction stage | • Annex 5, TM-EIAO | Implemented |
| \$5.4.1 | N3 | Install movable noise barriers (typical design is wooden framed barrier with a small-cantilevered on a skid footing with 25mm thick internal sound absorptive lining), acoustic mat or full enclosure, screen the noisy | Sreen the noisy plant items to be used at all construction | Contractor | All construction sites where practicable | Construction stage | • Annex 5, TM-EIAO | Implemented |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|--|--|-------------------------|---|-------------------------|--|--------------------------|
| | | plants including air compressors, generators and handheld breakers, etc. | sites | | | | | |
| S5.4.1 | N4 | Use 'Quiet plant' | Reduce the noise levels of plant items | Contractor | All construction sites where practicable | Construction stage | • Annex 5, TM-EIAO | Implemented |
| S5.4.1 | N5 | Loading/ unloading activities should be carried out inside the full enclosure of mucking out points. | Reduce the noise levels of loading/ unloading activities | Contractor | Mucking out locations | Construction stage | • Annex 5, TM-EIAO | Implemented |
| S5.4.1 | N6 | Sequencing operation of construction plants where practicable. | Operate sequentially within the same work site to reduce the construction airborne noise | Contractor | All construction sites where practicable | Construction stage | • Annex 5, TM-EIAO | Implemented |
| S5.4.1 | N7 | Implement a noise monitoring programme under EM&A programme. | Monitor the construction noise levels at the selected representative locations | Contractor | Selected rep. noise monitoring station | Construction stage | • TM-EIAO | Implemented |

Water Quality (Construction Phase)

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|-----------|---------------------|--|--|-------------------------|--|-------------------------|--|--------------------------|
| \$6.9.1.1 | W1 | In accordance with the Practice Note for Professional Persons on Construction Site Drainage, Environmental Protection Department, 1994 (ProPECC PN1/94), construction phase mitigation measures shall include the following: Construction Runoff • At the start of site establishment, perimeter cut-off drains to direct off-site water around the site should be constructed with internal drainage works and erosion and sedimentation control facilities implemented. Channels (both temporary and permanent drainage pipes and culverts), earth bunds or sand bag barriers should be provided on site to direct stormwater to silt removal facilities. The design of the temporary on-site drainage system will be undertaken by the contractor prior to the commencement of construction; • The dikes or embankments for flood protection should be implemented around the boundaries of earthwork areas. Temporary ditches should be provided to facilitate the runoff discharge into an appropriate watercourse, through a silt/ sediment trap. The sediment/ silt traps should be incorporated in the permanent drainage channels to enhance deposition rates; • The design of efficient silt removal facilities should be based on the guidelines in Appendix A1 of ProPECC PN 1/94, which states that the retention time for silt/ sand traps should be 5 minutes under | To minimize water quality impact from the construction site runoff and general construction activities | Contractor | All construction sites where practicable | Construction stage | Water Pollution Control Ordinance ProPECC PN 1/94 TM-EIAO TM-DSS | • Implemented |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|---|--|-------------------------|----------------------|-------------------------|--|--------------------------|
| | | maximum flow conditions. Sizes may vary depending upon the flow rate, but for a flow rate of 0.1 m3/s a sedimentation basin of 30 m3 would be required and for a flow rate of 0.5 m3/s the basin would be 150 m3. The detailed design of the sand/ silt traps shall be undertaken by the contractor prior to the commencement of construction; • All exposed earth areas should be completed and vegetated as soon as possible after earthworks have been completed, or alternatively, within 14 days of the cessation of earthworks where practicable. Exposed slope surfaces should be covered by tarpaulin or other means; • The overall slope of the site should be kept to a minimum to reduce the erosive potential of surface water flows, and all traffic areas and access roads protected by coarse stone ballast. An additional advantage accruing from the use of crushed stone is the positive traction gained during prolonged periods of inclement weather and the reduction of surface sheet flows; • All drainage facilities and erosion and sediment control structures should be regularly inspected and maintained to ensure proper and efficient operation at all times and particularly following rainstorms. Deposited silt and grit should be removed regularly and disposed of by spreading evenly over stable, vegetated areas; • Measures should be taken to minimize the ingress | | | | | | |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|---|--|-------------------------|----------------------|-------------------------|--|--------------------------|
| | | of site drainage into excavations. If the excavation of trenches in wet periods is necessary, they should be dug and backfilled in short sections wherever practicable. Water pumped out from trenches or foundation excavations should be discharged into storm drains via silt removal facilities; Open stockpiles of construction materials (for example, aggregates, sand and fill material) of more than 50m3 should be covered with tarpaulin or similar fabric during rainstorms. Measures should be taken to prevent the washing away of construction materials, soil, silt or debris into any drainage system; Manholes should always be adequately covered and temporarily sealed so as to prevent silt, construction materials or debris being washed into the drainage system and storm runoff being directed into foul sewers; Precautions be taken at any time of year when rainstorms are likely, actions to be taken when a rainstorm is imminent or forecasted, and actions to be taken during or after rainstorms are summarized in Appendix A2 of ProPECC PN 1/94. Particular attention should be paid to the control of silty surface runoff during storm events, especially for areas located near steep slopes; All vehicles and plant should be cleaned before leaving a construction site to ensure no earth, mud, debris and the like is deposited by them on roads. An adequately designed and site wheel washing | | | | | | |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|--|--|-------------------------|----------------------|-------------------------|--|--------------------------|
| | | facilities should be provided at every construction site exit where practicable. Wash-water should have sand and silt settled out and removed at least on a weekly basis to ensure the continued efficiency of the process. The section of access road leading to, and exiting from, the wheel wash bay to the public road should be paved with sufficient backfall toward the wheel wash bay to prevent vehicle tracking of soil and silty water to public roads and drains; Oil interceptors should be provided in the drainage system downstream of any oil/ fuel pollution sources. The oil interceptors should be emptied and cleaned regularly to prevent the release of oil and grease into the storm water drainage system after accidental spillage. A bypass should be provided for the oil interceptors to prevent flushing during heavy rain; Construction solid waste, debris and rubbish on site should be collected, handled and disposed of properly to avoid water quality impacts; All fuel tanks and storage areas should be provided with locks and sited on sealed areas, within bunds of a capacity equal to 110% of the storage capacity of the largest tank to prevent spilled fuel oils from reaching water sensitive receivers nearby; Adopt best management practices; All earth works should be conducted sequentially to limit the amount of construction runoff generated from exposed areas during the wet | | | | | | |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|-----------|---------------------|--|--|-------------------------|-----------------------|-------------------------|--|--------------------------|
| | | season (April to September) as far as practicable. | | | | | | |
| \$6.9.1.2 | W2 | Cut-&-cover tunneling work should be conducted sequentially to limit the amount of construction runoff generated from exposed areas during the wet season (April to September) as far as practicable. Uncontaminated discharge should pass through sedimentation tanks prior to off-site discharge; The wastewater with a high concentration of SS should be treated (e.g. by sedimentation tanks with sufficient retention time) before discharge. Oil interceptors would also be required to remove the oil, lubricants and grease from the wastewater; Direct discharge of the bentonite slurry (as a result of D-wall) is not allowed. It should be reconditioned and reused wherever practicable. Temporary storage locations (typically a properly closed warehouse) should be provided on site for any unused bentonite that needs to be transported away after all the related construction activities area completed. The requirements in ProPECC PN 1/94 should be adhered to in the handling and disposal of bentonite slurries. | To minimize construction water quality impact from tunneling works | Contractor | All tunneling portion | Construction stage | Water Pollution Control Ordinance ProPECC PN 1/94 TM-DSS TM-EIAO | • N/A |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|-----------|---------------------|---|--|-------------------------|--|-------------------------|--|--------------------------|
| \$6.9.1.3 | W3 | Portable chemical toilets and sewage holding tanks are recommended for handling the construction sewage generated by the workforce. A licensed contractor should be employed to provide appropriate and adequate portable toilets and be responsible for appropriate disposal and maintenance. | To minimize water quality from sewage effluent | Contractor | All construction sites where practicable | Construction stage | Water Pollution Control Ordinance TM-DSS | Implemented |
| S6.9.1.5 | W4 | No direct discharge of groundwater from contaminated areas should be adopted. A discharge license under the WPCO through the Regional Office of EPD for groundwater discharge should be applied. Prior to the excavation works within these potentially contaminated areas, the groundwater quality should be reviewed during the process of discharge license application. The compliance to the Technical Memorandum on Standards for Effluents Discharged into Drainage on Sewerage Systems, Inland and Coastal Waters (TM-DSS) and the existence of prohibited substance should be confirmed. If the review results indicated that the groundwater to be generated from the excavation works would be contaminated, the contaminated groundwater should be either properly treated in compliance with the requirements of the TM-DSS or properly | To minimize groundwater quality impact from contaminated area | Contractor | Excavation areas where contamination is found | Construction stage | Water Pollution Control Ordinance TM-DSS TM-EIAO | • Implemented |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|--|--|-------------------------|----------------------|-------------------------|--|--------------------------|
| | | If wastewater treatment is deployed, the wastewater treatment unit shall deploy suitable treatment process (e.g. oil interceptor / activated carbon) to reduce the pollution level to an acceptable standard and remove any prohibited substances (e.g. TPH) to undetectable range. All treated effluent from wastewater treatment plant shall meet the requirements as stated in TM-DSS and should be discharged into the foul sewers. If groundwater recharging wells are deployed, recharging wells should be installed as appropriate for recharging the contaminated groundwater back into the ground. The recharging wells should be selected at places where the groundwater quality will not be affected by the recharge operation as indicated in the Section 2.3 of TM-DSS. The baseline groundwater quality shall be determined prior to the selection of the recharge wells, and submit a working plan (including the laboratory analytical results showing the quality of groundwater at the proposed recharge location(s) as well as the pollutant levels of groundwater to be recharged) to EPD for agreement. Pollution levels of groundwater to be recharge shall not be higher than pollutant levels of ambient groundwater at the recharge well. Prior to recharge, any prohibited substances such as TPH products should be removed as necessary by installing the petrol | | | | | | |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|---|---|-------------------------|---|-------------------------|--|--|
| | | interceptor. | | | | | | |
| S6.9.1.6 | W6 | Accidental Spillage In order to prevent accidental spillage of chemicals, the following is recommended: All the tanks, containers, storage area should be bunded and the locations should be locked as far as possible from the sensitive watercourse and stormwater drains; The Contractor should register as a chemical waste producer if chemical wastes would be generated. Storage of chemical waste arising from the construction activities should be stored with suitable labels and warnings. Disposal of chemical wastes should be conducted in compliance with the requirements as stated in the Waste Disposal (Chemical Waste) (General) Regulation. | To minimize water quality impact from accidental spillage | Contractor | All construction site where practicable | Construction stage | Water Pollution Control Ordinance ProPECC PN 1/94 TM-EIAO TM-DSS | Implemented and rectified after observation. |
| | | | Waste Manage | ement (Construction | Waste) | | | |
| S7.4.1 | WM1 | Geological assessment should be carried out by competent persons on site during excavation to identify materials which are not suitable to use as aggregate in structural concrete (e.g. volcanic rock, Aplite dyke rock, etc.). Volcanic rock and Aplite dyke rock should be separated at the source sites as far as practicable and stored at designated | Separation of unsuitable rock from ending up at concrete batching plants and be turned into concrete for structural use | Contractor | All construction sites | Construction stage | • DEVB (W) No. 6/2010 | • N/A |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|--|---|-------------------------|------------------------|-------------------------|---|--------------------------|
| | | stockpile area preventing them from delivering to crushing facilities. The crushing plant operator should also be reminded to set up measures to prevent unsuitable rock from ending up at concrete batching plants and be turned into concrete for structural use. Details regarding control measures at source site and crushing facilities should be submitted by the Contractor for the Engineer to review and agree. In addition, site records should also be kept for the types of rock materials excavated and the traceability of delivery will be ensured with the implementation of Trip Ticket System and enforced by site supervisory staff as stipulated under DEVB TC(W) No. 6/2010 for tracking of the correct delivery to the rock crushing facilities for processing into aggregates. Alternative disposal option for the reuse of volcanic rock and Aplite Dyke rock, etc. should be explored. | | | | | | |
| \$7.5.1 | WM2 | Construction and Demolition Material Maintain temporary stockpiles and reuse excavated fill material for backfilling and reinstatement; Carry out on-site sorting; Make provisions in the Contract documents to allow and promote the use of recycled aggregates where appropriate; Adopt 'selective demolition' technique to demolish the existing structures and facilities with a view to recovering broken concrete effectively for recycling purpose, where possible; | Good site practice to minimize the waste generation and recycle the C&D materials as far as practicable so as to reduce the amount for final disposal | Contractor | All construction sites | Construction stage | Land (Miscellaneous Provisions) Ordinance Waste Disposal Ordinance ETWB TCW No. 19/2005 | • Implemented |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|---|---|-------------------------|----------------------|-------------------------|--|--------------------------|
| \$7.5.1 | WM3 | Implement a trip-ticket system for each works contract to ensure that the disposal of C&D materials are properly documented and verified; and Implement an enhanced Waste Management Plan similar to ETWBTC (Works) No. 19/2005 – "Environmental Management on Construction Sites" to encourage on-site sorting of C&D materials and to minimize their generation during the course of construction. C&D Waste | Good site | Contractor | All | Construction stage | • Land | • Implemented |
| | | Standard formwork or pre-fabrication should be used as far as practicable in order to minimize the arising of C&D materials. The use of more durable formwork or plastic facing for the construction works should be considered. Use of wooden hoardings should not be used, as in other projects. Metal hoarding should be used to enhance the possibility of recycling. The purchasing of construction materials will be carefully planned in order to avoid over ordering and wastage; The Contractor should recycle as much of the C&D materials as possible on-site. Public fill and C&D waste should be segregated and stored in different containers or skips to enhance reuse or recycling of materials and their proper disposal. Where practicable, concrete and masonry can be crushed and used as fill. Steel reinforcement bar can be used by scrap steel mills. Different areas of the | practice to minimize the waste generation and recycle the C&D materials as far as practicable so as to reduce the amount for final disposal | | construction sites | | (Miscellaneous Provisions) Ordinance • Waste Disposal Ordinance • ETWB TCW No. 19/2005 | |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|--|--|-------------------------|----------------------|--|---|--------------------------|
| | | sites should be considered for such segregation and storage. | | | | | | |
| \$7.5.1 | WM4 | Excavated Contaminated Soils Details of the mitigation measures on handling of the contaminated soil shall be referred to Section on Land Contamination below. | The contaminated soil will be excavated for on-site reuse | Contractor | РВН4 | Prior to commencement of construction works within the contaminated area | Practice Guide (PG) for Investigation and Remediation of Contaminated Land GN/GM for land contamination | Implemented |
| S7.5.1 | WM5 | ▲ All construction plant and equipment shall be designed and maintained to minimize the risk of silt, sediments, contaminants or other pollutants being released into the water column or deposited in the locations other than designated location; ◆ All vessels shall be sized such that adequate draft is maintained between vessels and the sea bed at all states of the tide to ensure that undue turbidity is not generated by turbulence from vessel movement or propeller wash; ◆ Before moving the vessels which are used for transporting dredged material, excess material shall be cleaned from the decks and exposed fittings of vessels and the excess materials shall never be dumped into the sea except at the | To control pollution due to marine sediment | Contractor | Along CKR alignment | Construction stage | • ETWB TCW No. 34/2002 | • Implemented |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|---|--|-------------------------|----------------------|-------------------------|--|--------------------------|
| | | approved locations; Adequate freeboard shall be maintained on barges to ensure that decks are not washed by wave action. The Contractors shall monitor all vessels transporting material to ensure that no dumping outside the approved location takes place. The Contractor shall keep and produce logs and other records to demonstrate compliance and that journeys are consistent with designated locations and copies of such records shall be submitted to the engineers; The Contractors shall comply with the conditions in the dumping licence. All bottom dumping vessels (Hopper barges) shall be fitted with tight fittings seals to their bottom openings to prevent leakage of material; The material shall be placed into the disposal pit by bottom dumping; Contaminated marine mud shall be transported by spit barge of not less than 750m3 capacity and capable of rapid opening and discharge at the disposal site; Discharge shall be undertaken rapidly and the hoppers shall be closed immediately. Material adhering to the sides of the hopper shall not be washed out of the hopper and the hopper shall remain closed until the barge returns to the disposal site. For Type 3 special disposal treatment, sealing of | | | | | | |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|---|--|-------------------------|------------------------|-------------------------|---|--|
| | | contaminant with geosynthetic containment before dropping designated mud pit would be a possible arrangement. A geosynthetic containment method is a method whereby the sediments are sealed in geosynthetic containers and, the containers would be dropped into the designated contaminated mud pit where they would be covered by further mud disposal and later by the mud pit capping at the disposal site, thereby fulfilling the requirements for fully confined mud disposal. | | | | | | |
| \$7.5.1 | WM6 | Chemical Waste Chemical waste that is produced, as defined by Schedule 1 of the Waste Disposal (Chemical Waste) (General) Regulation, should be handled in accordance with the Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes; Containers used for the storage of chemical wastes should be suitable for the substance they are holding, resistant to corrosion, maintained in a good condition, and securely closed, have a capacity of less than 450 L unless the specification has been approved by EPD, and display a label in English and Chinese in accordance with instructions prescribed in Schedule 2 of the regulation; The storage area for chemical wastes should be clearly labelled and used solely for the storage of chemical waste, enclosed on at least 3 sides, have an impermeable floor and bunding of sufficient | Control the chemical waste and ensure proper storage, handling and disposal | Contractor | All construction sites | Construction stage | Waste Disposal (Chemical Waste) (General) Regulation Code of Practice on the Packaging, Labelling and Storage of Chemical Waste | Implemented and rectified after observation. |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|--|---|-------------------------|------------------------|-------------------------|--|--------------------------|
| \$7.5.1 | WM7 | capacity to accommodate 110% of the volume of the largest container or 20% of the total volume of waste stored in that area, whichever is the greatest, have adequate ventilation, covered to prevent rainfall entering, and arranged so that incompatible materials are adequately separated; • Disposal of chemical waste should be via a licensed waste collector, be to a facility licensed to receive chemical waste, such as the Chemical Waste Treatment Centre which also offers a chemical waste collection service and can supply the necessary storage containers, or be to a reuser of the waste, under approval from EPD. General Refuse • General refuse generated on-site should be stored in enclosed bins or compaction units separately from construction and chemical wastes; • A reputable waste collector should be employed by the Contractor to remove general refuse from the site, separately from construction and chemical wastes, on a daily basis to minimize odour, pest and litter impacts. Burning of refuse on construction sites is prohibited by law. • Aluminum cans are often recovered from the waste stream by individual collectors if they are segregated and made easily accessible. Separate labelled bins for their deposit should be provided if feasible; • Office wastes can be reduced through the recycling of paper if volumes are large enough to warrant | Minimize production of the general refuse and avoid odour, pest and litter impacts | Contractor | All construction sites | Construction stage | Waste Disposal Ordinance | • Implemented |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|---------------------------|---------------------|--|--|-------------------------|----------------------|--|--|--------------------------|
| | | collection. Participation in a local collection scheme should be considered by the Contractor. | | | | | | |
| | | | Land Contamir | nation | | | | |
| S8.9 & Appendix 8.4 | | Excavation of the Contaminated Soil Prior to commencement of the excavation works at the contamination zone, the zone should be clearly marked out on site and the surface levels recorded. Excavation of contaminated material should be undertaken using dedicated earth-moving plant. The excavated contaminated soils would be stockpiled at designated area on site and covered by sheet to prevent dispersion of contamination during stockpiling. The Contractor should pay attention to the selection of suitable groundwater lowering schemes and discharge points if the groundwater table is higher than the contaminated soils during excavation. The Contractor should also obtain a valid Water Pollution Control Ordinance (WPCO) discharge licence from EPD where applicable. | The contaminated soil will be excavated for on-site reuse | Contractor | РВН4 | Prior to commencement of construction works within the contaminated area | Practice Guide (PG) for Investigation and Remediation of Contaminated Land Guidance Notes for Contaminated Land Assessment and Remediation Guidance Manual for Use of Risk-Based | • N/A |
| S8.9 & Appendix 8.4 | LC3 | Following completion of the excavation to the specified depth, at least one sample from the base of the excavation and four samples evenly distributed along the boundary of the excavation shall be taken for a closure assessment testing. The acceptance criterion is shown below: | | | | | Remediation Goals (RBRGs) for Contaminated Land Management | • N/A |

| EIA Ref. | EM&A Log Ref. | Reco | Recommended Mitigation Measures | | | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------|---------------------|---|--|------------------------|---------------|-------------------------|----------------------|-------------------------|--|--------------------------|
| | | Locations | Testing | Acceptance | | | | | | |
| | | | requirement | Criteria | | | | | | |
| | | PBH4 PCBs RBRGs (Public Park) | | | | | | | | |
| | | | | | | | | | | |
| | | • If the results of analysis below the RBRGs (Public Park), no further excavation will be required. | | | | | | | | |
| | | If the analysis | s indicates presence o | of contamination (i.e. | | | | | | |
| | | noncomplian | noncompliance of the acceptance criteria), further | | | | | | | |
| | | excavation shall be carried out in 0.5m increment vertically and/or horizontally depending on the location(s) of the sample(s) which has exceeded the | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | npling shall also be | | | | | | |
| | | | or compliance testi | ng. The process of | | | | | | |
| | | excavation, | Laamplianaa tastina | should continue until | | | | | | |
| | | | | noved and should be | | | | | | |
| | | | a Land Contamination | | | | | | | |
| Appendix | LC4 | | | emonstrate adequate | | | | | | • N/A |
| 8.4 | 104 | | | submitted to EPD for | | | | | | · N/A |
| | | | | nmencement of any | | | | | | |
| | | | | within the sites. No | | | | | | |
| | | construction | /development works | shall be carried out | | | | | | |
| | | prior to the endorsement of the RR by EPD. | | | | | | | | |
| | | | | | | Hazard to Life | | | | |
| S9.18 | Н8 | The driver a | and his assistant s | hould be physically | To reduce the | Contractor | Works areas | Construction stage | - | • N/A |
| | | healthy, exp | erienced and have | good safe driving | risk during | | at which | | | |
| | | | | ld a proper driving | explosives | | explosives | | | |
| | | licence for th | ne approved transpo | rt truck. Dedicated | transport | | would be | | | |


| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------------------------|---------------------|---|--|-------------------------|---|-------------------------|--|--------------------------|
| | | training programme and regular road safety briefing sessions/ workshops should be provided to enhance their safe driving attitude and practice. Smoking should be strictly prohibited. | | | used | | | |
| S9.18 | Н9 | Emergency response plans in case of road accident should be prepared and implemented. The driver and his assistant should be familiar with the emergency procedures including evacuation, and proper communication/ fire-fighting equipment should be provided to the driver and his assistant. | To reduce the risk during explosives transport | Contractor | Works areas at which explosives would be used | Construction stage | - | • N/A |
| | | | Land | dscape & Visual | | | | |
| S10.10.1 Table 10.11 | LV3 | Good Site Management Large temporary stockpiles of excavated material shall be covered with unobtrusive sheeting to prevent dust and dirt spreading to adjacent landscape areas and vegetation, and to create a neat and tidy visual appearance. Construction plant and building material shall be orderly and carefully stored in order to create a neat and tidy visual appearance. | Minimize visual impact | Contractor | Within Project site | Construction stage | - | Implemented |
| S10.10.1 Table 10.11 | LV4 | Screen Hoarding • Decorative screen hoarding should be erected to screen the public from the construction area. It should be designed to be compatible with the existing urban context. | Minimize visual impact | Contractor | Within Project site | Construction stage | - | Implemented |
| S10.10.1 Table 10.11 | LV5 | Lighting Control during Construction • All lighting in the construction site shall be carefully controlled to minimize light pollution and night-time glare to nearby residencies and GIC. | Minimize visual impact | Contractor | Within Project site | Construction stage | - | Implemented |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------------------------|---------------------|--|--|-------------------------|------------------------|-------------------------|--|--------------------------|
| | | The Contractor shall consider other security measures, which shall minimize the visual impacts. | | | | | | |
| S10.10.1 Table 10.11 | LV6 | Erosion Control The potential for soil erosion shall be reduced by minimizing the extent of vegetation disturbance on site and by providing a protective cover over newly exposed soil. | Minimize landscape impact | Contractor | Within Project site | Construction stage | - | Implemented |
| S10.10.1 Table 10.11 | LV7 | Tree Protection & Preservation • Carefully protected during construction. Tree protection measures will be detailed at the Tree Removal Application stage and plans submitted to the relevant Government Department for approval in due course in accordance with ETWB TC no. 3/2006. | Minimize landscape and visual impact | Contractor | Within Project site | Construction stage | 'Guidelines for Tree Risk Management and Assessment Arrangement on an Area Basis and on a Tree Basis', Greening, Landscape and Tree Management (GLTM) Section, DEVB Latest recommended horticultural practices from GLTM Section, DEVB | • Implemented |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|----------------------------|---------------------|--|--|-------------------------|---|-----------------------------|--|--------------------------|
| S10.10.1 Table 10.11 | LV8 | Tree Transplantation • For trees unavoidably affected by the Project that have to be removed, where practical transplantation will be chosen as the top priority method of removal. If this is not possible or practical compensatory planting will be provided for trees unavoidably felled (See LV10). For trees unavoidably affected by the Project works that are transplanted, transplantation must be carried out in accordance with ETWB TCW 2/2004 and 3/2006. | Minimize landscape and visual impact | Contractor | Within Project site and designated off-site locations | Prior to Construction stage | ETWB TCW 3/2006 Latest recommended horticultural practices from Greening, Landscape and Tree Management (GLTM) Section, DEVB ETWB TCW 2/2004 | • N/A |
| S10.10.1 Table 10.11 | LV9 | Compensatory Planting For trees unavoidably affected by the Project that have to be removed, where practical transportation will be chosen as the top priority method of removal but if this is not possible or practical compensatory planting will be provided for trees unavoidably felled. All felled trees shall be compensated for by planting trees to the satisfaction of relevant Government projects. Required numbers and locations of compensatory trees shall be determined and agreed separately with Government during the Tree Felling Application process under ETWBTC 3/2006. Compensatory tree planting may be incorporated into public open spaces and along roadside amenity areas affected by the construction works | Minimize visual impact and also enhance landscape | Contractor | Within Project site | Construction stage | ETWB TCW 3/2006 Latest recommended horticultural practices from Greening, Landscape and Tree Management (GLTM) Section, DEVB ETWB TCW 2/2004 | • N/A |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|-----------------------------|---------------------|---|--|-------------------------|------------------------|-------------------------|---|--------------------------|
| | | and therefore be part of the bigger wider planting plans. Onsite compensation planting is preferred but if necessary, additional receptor sites outside the Works Area shall be agreed separately with Government during the Tree Felling Application process. | | | | | | |
| \$10.10.1 Table 10.11 | LV10 | Screen Planting Tall screen/buffer trees, shrubs and climbers should be planted, in so far as is possible, to soften and screen proposed structures such as roads and central strip, vertical edges and buildings and to enhance streetscape greening effect where appropriate. Indiscriminate use of trees for screening must be avoided and the principle of 'right tree for the right place' must be followed. This detail will be provided at the Detailed Design stage. This measure may additionally form part of the compensatory planting and will improve and create a pleasant pedestrian environment. | Minimize visual impact and also enhance landscape. | Contractor | Within Project Site | Construction Phase | Guidelines on Greening of Noise Barriers, issued April 2012, GLTMS, DevB ETWB TCW 2/2004 | • N/A |
| S10.10.1 Table 10.11 | LV12 | Reinstatement All works areas, excavated areas and disturbed areas for tunnel construction and temporary road diversion or any other proposed works shall be reinstated to former conditions or better, with reasonable landscape treatment and to the satisfaction of the relevant Government departments. (Specific mitigation for disturbance to public open space is detailed separately under LV14) | Minimize landscape impact | Contractor | Within Project Site | Construction Phase | • N/A | • N/A |

| EIA Ref. | EM&A Log Ref. | Recommended Mitigation Measures | Objectives of the Recommended Measures & Main Concerns to address | Implementation Agent | Location / Timing | Implementation Stage | Requirements and/ or standards to be achieved | Implementation Status |
|------------|---------------------|--|--|---------------------------------------|---|-------------------------|--|--------------------------|
| | | | Cultural Heritage | Impact (Construct | ion Phase) | | | |
| S11.4.4 | CH1 | The contractor should be alerted during the construction on the possibility of locating archaeological remains and as a precautionary measure, AMO shall be informed immediately in case of discovery of antiquities or supposed antiquities in the subject sites. | To preserve any cultural heritage items which may be removed and damaged by the excavation | Contractor | During construction works for cut and cover tunnels | Construction stage | AMOs requirements | • Implemented |
| | | | | EM&A Project | | | | |
| \$13.2 | EM1 | An Independent Environmental Checker needs to be employed as per the EM&A Manual | Control EM&A Performance | Highways Department | All construction sites | Construction stage | • EIAO Guidance Note No. 4/2010 • TM-EIAO | • Implemented |
| S13.2-13.4 | EM2 | An Environmental Team needs to be employed as per the EM&A Manual; Prepare a systematic Environmental Management Plan to ensure effective implementation of the mitigation measures; An environmental impact monitoring needs to be implemented by the Environmental Team to ensure all the requirements given in the EM&A Manual are fully complied with. | Perform environmental monitoring & auditing | Highways Department/ Contractor | All construction sites | Construction stage | • EIAO Guidance Note No. 4/2010 • TM-EIAO | Implemented |



July 2020

| SUNDAY | MONDAY | TUESDAY | WEDNESDAY | THURSDAY | FRIDAY | SATURDAY |
|--------|--|---------|--|---|---|-------------------------------|
| 28 | 29 | 30 | 1 | 2 | 3 | 4 |
| 5 | 6 Impact Dust monitoring (E-A1) | 7 | 8 | 9 | 10 | Impact Dust monitoring (E-A1) |
| 12 | 13 | 14 | 15 | 16 | 17 Impact Dust monitoring (E-A1) | 18 |
| 19 | 20 | 21 | 22 24-hour Dust monitoring for E-Al (Supplementary monitoring due to short-circuited electricity supply) | 23 Impact Dust monitoring (E-A1) | 24 | 25 |
| 26 | 27 | 28 | 29 Impact Dust monitoring (E-A1) | 30 | 31 | 1 |
| 2 | 3 | | | | | |

Appendix H
Calibration Certificates
(Air Monitoring)



SIBATA SCIENTIFIC TECHNOLOGY LTD.

1-1-62, Nakane, Soka, Saitama, 340-0005 Japan

TEL: 048-933-1582 FAX: 048-933-1591

CALIBRATION CERTIFICATE

Date: August 28th, 2019

Equipment Name : Digital Dust Indicator, Model LD-5R

 Code No.
 : 080000-72

 Quantity
 : 1 unit

 Serial No.
 : 851820

 Sensitivity
 : 0.001 mg/m3

Sensitivity Adjustment : 640

Scale Setting : August 23rd, 2019

We hereby certify that the above mentioned instrument has been calibrated satisfactory.

Sincerely

SIBATA SCIENTIFIC TECHNOLOGY LTD.

Tong Zhang

Overseas & New Business Group

Overseas Sales Department



TE-5028A

RECALIBRATION DUE DATE:

October 10, 2020

Calibration Certification Information

Cal. Date: October 10, 2019 Rootsmeter S/N: 438320

Ta: 296

Operator: Jim Tisch Calibration Model #:

Calibrator S/N: 3702

Pa: 748.03

mm Hg

| Run | Vol. Init (m3) | Vol. Final (m3) | ΔVol. (m3) | ΔTime (min) | ΔP (mm Hg) | ΔH (in H2O) |
|-----|-------------------|--------------------|---------------|-------------|---------------|----------------|
| 1 | 1 | 2 | 1 | 1.3100 | 4.1 | 1.50 |
| 2 | 3 | 4 | 1 | 1.0240 | 6.7 | 2.50 |
| 3 | 5 | 6 | 1 | 0.9260 | 8.0 | 3.00 |
| 4 | 7 | 8 | 1 | 0.8620 | 9.4 | 3.50 |
| 5 | 9 | 10 | 1 | 0.6540 | 16.2 | 6.00 |

| | | Data Tabulat | ion | | |
|--------|----------|---|--------|----------|------------|
| Vstd | Qstd | $\sqrt{\Delta H \left(\frac{Pa}{Pstd}\right) \left(\frac{Tstd}{Ta}\right)}$ | | Qa | √∆H(Ta/Pa) |
| (m3) | (x-axis) | (y-axis) | Va | (x-axis) | (y-axis) |
| 0.9855 | 0.7523 | 1.2192 | 0.9945 | 0.7592 | 0.7704 |
| 0.9820 | 0.9590 | 1.5739 | 0.9910 | 0.9678 | 0.9946 |
| 0.9803 | 1.0586 | 1.7242 | 0.9893 | 1.0684 | 1.0895 |
| 0.9784 | 1.1351 | 1.8623 | 0.9874 | 1.1455 | 1.1768 |
| 0.9694 | 1.4823 | 2.4383 | 0.9783 | 1.4959 | 1.5409 |
| | m= | 1.66723 | | m= | 1.04399 |
| QSTD | b= | -0.03281 | QA | b= | -0.02074 |
| | r= | 0.99991 | ٠., | r= | 0.99991 |

| | Calculation | ns | | |
|-------|--|---------------|--|--|
| Vstd= | ΔVol((Pa-ΔP)/Pstd)(Tstd/Ta) | Va= | ΔVol((Pa-ΔP)/Pa) | |
| Qstd= | Vstd/ΔTime | Qa= Va/ΔTime | | |
| | For subsequent flow ra | te calculatio | ns: | |
| Qstd= | $1/m\left(\left(\sqrt{\Delta H\left(\frac{Pa}{Pstd}\right)\left(\frac{Tstd}{Ta}\right)}\right)-b\right)$ | Qa= | $1/m\left(\left(\sqrt{\Delta H\left(Ta/Pa\right)}\right)-b\right)$ | |

| | Standard Conditions |
|----------------|------------------------------|
| Tstd: | 298.15 °K |
| Pstd: | 760 mm Hg |
| | Key |
| ΔH: calibrator | manometer reading (in H2O) |
| ΔP: rootsmete | er manometer reading (mm Hg) |
| Ta: actual abs | olute temperature (°K) |
| Pa: actual bar | ometric pressure (mm Hg) |
| b: intercept | |
| m: slope | |

RECALIBRATION

US EPA recommends annual recalibration per 1998 40 Code of Federal Regulations Part 50 to 51, Appendix B to Part 50, Reference Method for the Determination of Suspended Particulate Matter in the Atmosphere, 9.2.17, page 30.

Tisch Environmental, Inc. 145 South Miami Avenue Village of Cleves, OH 45002

www.tisch-env.com

TOLL FREE: (877)263-7610 FAX: (513)467-9009

InnoTech Instrumentation Co. Ltd.

創新科儀有限公司

HIVOL SAMPLER CALIBRATION DATA SHEET (TSP)

Site Information

| Location: | Emax | Site ID: | | Date: | 26-Jun-2020 |
|------------|------|----------|----------|-----------|-------------|
| Serial No: | 1085 | Model: | TE-5170X | Operator: | Polar Chan |

Ambient Condition

| Corrected Pressure (mm Hg): | 754.8 | Temperature (deg K): | 302.8 |
|-----------------------------|-------|----------------------|-------|
|-----------------------------|-------|----------------------|-------|

Calibration Orifice

| Model: | TE-5028A | Slope: | 1.66723 |
|-----------------------|-----------|--------------|----------|
| Serial No.: | 3702 | Intercept: | -0.03281 |
| Calibration Due Date: | 10-Oct-20 | Corr. Coeff: | 0.99991 |

Calibration Data

| Plate or | In,H2O | Qa, X-Axis | I, CFM | IC, Y-Axis |
|----------|--------|------------|---------|-------------|
| Test # | (in) | (m3/min) | (chart) | (corrected) |
| 1 | 1.76 | 0.807 | 30.4 | 30.03 |
| 2 | 2.29 | 0.917 | 32.3 | 31.96 |
| 3 | 2.48 | 0.953 | 33.0 | 32.63 |
| 4 | 3.03 | 1.051 | 34.6 | 34.21 |
| 5 | 3.23 | 1.086 | 35.5 | 35.05 |

Sampler Calibtation Relationship (Qa on x-axis, IC on y-axis)

| m= | 17.6839 | b= | 15.7467 | Corr. Coeff= | 0.9991 |
|--------|------------------|----|---------|--------------|--------|
| Sample | r set point(SSP) | 38 | CFM | | |

Calculations

m = calibrator Qstd slopeb = calibrator Qstd interceptTa = actual temperature during calibration (deg K)

Pa = actual pressure during calibration (mm Hg)

Tstd = 298 deg KPstd = 760 mm Hg

For subsequent calculation of sampler flow: (1.21*m+b)/[Sqrt(298/Tav)(Pav/760)]

Checked by: Date: 26-Jun-20

InnoTech Instrumentation Co. Ltd.

創新科儀有限公司

HIVOL SAMPLER CALIBRATION DATA SHEET (TSP)

Site Information

| Location: | Emax | Site ID: | | Date: | 11-Jul-2020 | |
|------------|------|----------|----------|-----------|-------------|--|
| Serial No: | 1085 | Model: | TE-5170X | Operator: | Polar Chan | |

Ambient Condition

| Corrected Prossure (mm Hg): | 755.6 | Tomporature (dea K): | 202.4 |
|-----------------------------|-------|----------------------|-------|
| Corrected Pressure (mm Hg): | 755.6 | Temperature (deg K): | 303.4 |

Calibration Orifice

| Model: | TE-5028A | Slope: | 1.66723 |
|-----------------------|-----------|--------------|----------|
| Serial No.: | 3702 | Intercept: | -0.03281 |
| Calibration Due Date: | 10-Oct-20 | Corr. Coeff: | 0.99991 |

Calibration Data

| Plate or | In,H2O | Qa, X-Axis | I, CFM | IC, Y-Axis |
|----------|--------|------------|---------|-------------|
| Test # | (in) | (m3/min) | (chart) | (corrected) |
| 1 | 1.86 | 0.828 | 30.8 | 30.42 |
| 2 | 2.31 | 0.920 | 32.7 | 32.30 |
| 3 | 2.66 | 0.986 | 34.0 | 33.59 |
| 4 | 3.01 | 1.048 | 35.4 | 34.94 |
| 5 | 3.36 | 1.106 | 36.8 | 36.36 |

Sampler Calibtation Relationship (Qa on x-axis, IC on y-axis)

| m= | 21.1203 | b= | 12.8707 | Corr. Coeff= | 0.9991 |
|----|---------|----|---------|--------------|--------|
| | | | | | |

Calculations

CFM

39

I = actual chart response m = calibrator Qstd slope

b = calibrator Qstd intercept

Ta = actual temperature during calibration (deg K)
Pa = actual pressure during calibration (mm Hg)

Sampler set point(SSP)

Tstd = 298 deg K

Pstd = 760 mm Hg

For subsequent calculation of sampler flow: (1.21*m+b)/[Sqrt(298/Tav)(Pav/760)]

Checked by: Date: 11-Jul-20

InnoTech Instrumentation Co. Ltd.

創新科儀有限公司

HIVOL SAMPLER CALIBRATION DATA SHEET (TSP)

Site Information

| Location: | Emax | Site ID: | | Date: | 22-Jul-2020 | |
|------------|------|----------|----------|-----------|-------------|--|
| Serial No: | 1049 | Model: | TE-5170X | Operator: | Polar Chan | |

Ambient Condition

| Corrected Pressure (mm Hg): | 757.0 | Temperature (deg K): | 303 U |
|-----------------------------|-------|----------------------|-------|
| Corrected Pressure (mm mg): | /5/.0 | remperature (deg K): | 303.0 |

Calibration Orifice

| Model: | TE-5028A | Slope: | 1.66723 |
|-----------------------|-----------|--------------|----------|
| Serial No.: | 3702 | Intercept: | -0.03281 |
| Calibration Due Date: | 10-Oct-20 | Corr. Coeff: | 0.99991 |

Calibration Data

| Plate or | In,H2O | Qa, X-Axis | I, CFM | IC, Y-Axis |
|----------|--------|------------|---------|-------------|
| Test # | (in) | (m3/min) | (chart) | (corrected) |
| 1 | 1.95 | 0.849 | 32.4 | 32.03 |
| 2 | 2.34 | 0.928 | 34.0 | 33.61 |
| 3 | 2.72 | 0.999 | 35.1 | 34.74 |
| 4 | 3.06 | 1.058 | 36.2 | 35.85 |
| 5 | 3.30 | 1.098 | 37.0 | 36.61 |

Sampler Calibtation Relationship (Qa on x-axis, IC on y-axis)

| m= | 18.1758 | b= | 16.6376 | Corr. Coeff= | 0.9995 |
|------|---------------------|----|---------|--------------|--------|
| | | | | | |
| Samp | oler set point(SSP) | 39 | CFM | | |

Calculations

 $Qstd = 1/m[Sqrt(H2O(Pa/Pstd)(Tstd/Ta))-b] \qquad m = sampler slope \\ IC = I[Sqrt(Pa/Pstd)(Tstd/Ta)] \qquad b = sampler intercept \\ I = chart response \\ Ostd = standard flow rate \qquad Tay = average temperate$

b = calibrator Qstd interceptTa = actual temperature during calibration (deg K)Pa = actual pressure during calibration (mm Hg)

Tstd = 298 deg K

m = calibrator Qstd slope

Pstd = 760 mm Hg
For subsequent calculation of sampler flow: (1.21*m+b)/[Sqrt(298/Tav)(Pav/760)]

Checked by: Date: 22-Jul-20



Appendix I
The Certification of Laboratory with HOKLAS
Accredited Analytical Tests



Hong Kong Accreditation Service 香港認可處

Certificate of Accreditation

認可證書

This is to certify that 特此證明

ACUMEN LABORATORY AND TESTING LIMITED

浩科檢測中心有限公司

Lot 12, Tam Kon Shan Road, North Tsing Yi, New Territories, Hong Kong 香港新界青衣北担杆山路12路段

has been accepted by the HKAS Executive, on the recommendation of the Accreditation Advisory Board, as a 在認可諮詢委員會的建議下獲香港認可處執行機關接受為

> **HOKLAS Accredited Laboratory** 「香港實驗所認可計劃」認可實驗所

This laboratory meets the requirements of ISO/IEC 17025:2005 and it has been accredited for performing specific tests or calibrations as listed in the scope of accreditation within the test category of

Environmental Testing

此實驗所符合ISO/IEC 17025:2005所訂的要求 並獲認可進行載於認可範圍內下述測試類別中的指定測試或校正工作

環境測試

This accreditation to ISO/IEC 17025:2005 demonstrates technical competence for a defined scope and the operation of a laboratory quality management system (see joint IAF-ILAC-ISO Communiqué). 此項 ISO/IEC 17025:2005 的認可資格證明此實驗所具備指定範疇內所須的技術能力並 實施一套實驗所質量管理體系(見國際認可論壇、國際實驗所認可合作組織及國際標準化組織的聯合公報)。

The common seal of the Hong Kong Accreditation Service is affixed hereto by the authority of the HKAS Executive 現經香港認可處執行機關授權在此蓋上香港認可處的印章

WONG Wang-wah, Executive Administrator

執行幹事 黃宏華 Issue Date: 16 July 2014

簽發日期:二零一四年七月十六日

註冊號碼:


Registration Number : HOKLAS 241

Date of First Registration: 16 July 2014 首次註冊日期:二零一四年七月十六日

This certificate is issued subject to the terms and conditions laid down by HKAS 本證書按照香港認可處訂立的條款及條件發出

L 001195







Appendix K
Monitoring Data (Air Monitoring)


Location: Hong Kong International Trade and Exhibition Centre (E-A1)

Monitoring date: 6, 11, 17, 23 and 29 Jul 2020

Parameter: TSP 1-hour
Other Factors: Nearby traffic

| | | 1-hour TSP (μg/m³) | | | | | |
|------------|---------|--------------------|---------------------------------|---------------------------------|---------------------------------|--|--|
| Date | Weather | Start Time | 1 st Hour (μg/m³) | 2 nd Hour (μg/m³) | 3 rd Hour (μg/m³) | | |
| 06/07/2020 | Sunny | 9:28 | 44 | 53 | 50 | | |
| 11/07/2020 | Sunny | 9:35 | 41 | 50 | 47 | | |
| 17/07/2020 | Sunny | 9:41 | 37 | 46 | 42 | | |
| 23/07/2020 | Sunny | 10:06 | 31 | 38 | 34 | | |
| 29/07/2020 | Fine | 9:24 | 36 | 45 | 43 | | |

Figure 1: Graphical Illustration of Measured 1-hour TSP ($\mu g/m^3$) Levels at E-A1



Location: Hong Kong International Trade and Exhibition Centre (E-A1)


Monitoring date: 6, 11, 17, 23 and 29 Jul 2020

Parameter: TSP 24-hour Other Factors: Nearby traffic

| Date of Calibration: | 26-Jun-20 | Slope = | 17.6839 |
|-----------------------|-----------|-------------|---------|
| Calibration due date: | 10-Jul-20 | Intercept = | 15.7467 |
| Date of Calibration: | 11-Jul-20 | Slope = | 21.1203 |
| Calibration due date: | 25-Jul-20 | Intercept = | 12.8707 |
| Date of Calibration: | 22-Jul-20 | Slope = | 18.1758 |
| Calibration due date: | 5-Aug-20 | Intercept = | 16.6376 |


| Start Date | Weather Condition | Hanse Time Chart Reading | | Avg Air Temp | Avg Atmospheric Pressure | Flow Rate | Standard Air Volume | Filter Weight | ; (g) | Particulate weight | Conc. | | | | |
|------------|----------------------|----------------------------|---------|-----------------|--------------------------------|----------------|---------------------------|---------------|---------------|-----------------------|---------------------------|----------------|--------|--------|----------------------|
| | Condition | Initial | Final | Actual (min) | Min | Max | Avg | (°C) | (mm hPa) | (m³/min) | (m ³) | Initial | Final | (g) | (μg/m ³) |
| 6/7/2020 | Sunny | 1633.66 | 1657.66 | 1440.00 | 40 | 40 | 40.0 | 30.1 | 1007.4 | 1.34 | 1926 | 2.7158 | 2.7609 | 0.0451 | 23 |
| 11/7/2020 | Sunny | 1657.82 | 1681.82 | 1440.00 | 39 | 40 | 39.5 | 30.4 | 1007.4 | 1.23 | 1774 | 2.6984 | 2.7556 | 0.0572 | 32 |
| 17/7/2020 | | | Resi | ult was void | ed due to un | stable electri | city supply | , substitute | 24-hour TSP n | nonitoring wa | s carried out | on 22 Jul 2020 |). | | |
| 22/7/2020 | Sunny | 2021.86 | 2045.86 | 1440.00 | 39 | 40 | 39.5 | 30.0 | 1009.3 | 1.23 | 1771 | 2.6971 | 2.7457 | 0.0486 | 27 |
| 23/7/2020 | Sunny | 2045.90 | 2069.90 | 1440.00 | 39 | 40 | 39.5 | 31.0 | 1009.0 | 1.23 | 1765 | 2.7266 | 2.7801 | 0.0535 | 30 |
| 29/7/2020 | Fine | 2069.92 | 2093.92 | 1440.00 | 40 | 40 | 40.0 | 28.8 | 1005.7 | 1.25 | 1805 | 2.7004 | 2.7378 | 0.0374 | 21 |

Figure 2: Graphical Illustration of Measured 24-hour TSP ($\mu g/m^3$) Levels at E-A1





WIND DIRECTION DATA FOR 6, 11, 17, 22, 23 and 29 Jul 2020

Wind Direction:




Wind Direction:







Wind Direction:




Wind Direction:






Wind Direction:





Wind Direction:






Wind Direction:







WIND SPEED DATA FOR 6, 11, 17, 22, 23 and 29 Jul 2020




Wind Speed:



Wind Speed:









Wind Speed:




Wind Speed:






Wind Speed:



Wind Speed:



Appendix L Waste Flow Table

Monthly Summary Waste Flow Table

Name of Department: Highways Department

Monthly Summary Waste Flow Table for Jul 2020

Contract No. / Works Order No.: <u>HY/2018/02</u>

Monthly Summary Waste Flow Table for Jul 2020

[to be submitted not later than the 15th day of each month following reporting month] (All quantities shall be rounded off to 1 decimal place.)

| | | | Actual Quantities of Inert Co | nstruction Waste Genera | ted Monthly | |
|-------------------|---|---|-------------------------------|------------------------------------|--------------------------------------|----------------------|
| Month | (a)=(b)+(c)+(d)+(e)+ (f)+ (g)+ (h)+ (i)+ (j)+ (k) Total Quantity Generated | (b) Hard Rock and Large Broken Concrete | (c) Reused in the Contract | (d) Reused in other Projects | (e) Disposed of as Public Fill | (f) Imported Fill |
| | (in 'tonnes) | (in 'tonnes) | (in 'tonnes) | (in 'tonnes) | (in 'tonnes) | (in 'tonnes) |
| Jan-20 | 3,242.73 | 0.00 | 0.00 | 0.00 | 3,208.12 | 0.00 |
| Feb-20 | 4,251.78 | 0.00 | 0.00 | 0.00 | 4,218.94 | 0.00 |
| Mar-20 | 5,312.07 | 0.00 | 140.00 | 0.00 | 5,155.25 | 0.00 |
| Apr-20 | 5,249.68 | 0.00 | 0.00 | 0.00 | 5,234.88 | 0.00 |
| May-20 | 4,693.57 | 0.00 | 0.00 | 0.00 | 4,664.85 | 0.00 |
| Jun-20 | 16,196.73 | 0.00 | 0.00 | 8,228.00 | 7,931.83 | 0.00 |
| Sub-total | 38,946.55 | 0.00 | 140.00 | 8,228.00 | 30,413.87 | 0.00 |
| Jul-20 | 11,703.35 | 0.00 | 0.00 | 2,276.00 | 9,389.95 | 0.00 |
| Aug-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Sep-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Oct-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Nov-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Dec-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Total | 50,649.90 | 0.00 | 140.00 | 10,504.00 | 39,803.82 | 0.00 |
| 2019 | 7,473.53 | 190.0 | 140.00 | 0.00 | 6,643.48 | 0.00 |
| Accumulated Total | 58,123.43 | 190.0 | 280.00 | 10,504.00 | 46,447.30 | 0.00 |

| | Actual Quantities of Non-inert Construction Waste Generated Monthly | | | | | | | | |
|-------------------|---|---------------|-----------|--|-----------|-----------------------|-----------|--|--------------|
| Month | | (g) Metals | | (h) Paper/ cardboard packaging (i) Plastics | | (j) Chemical Waste | | (k) Others, e.g. General Refuse disposed at Landfill | |
| | (in '(| 000kg) | (in '0 | 00kg) | (in '00 | (in '000kg) | | 000kg) | (in 'tonnes) |
| | generated | recycled | generated | recycled | generated | recycled | generated | recycled | generated |
| Jan-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 34.61 |
| Feb-20 | 11.94 | 11.94 | 0.55 | 0.55 | 0.00 | 0.00 | 0.00 | 0.00 | 20.35 |
| Mar-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 16.82 |
| Apr-20 | 0.00 | 0.00 | 0.15 | 0.15 | 0.00 | 0.00 | 0.00 | 0.00 | 14.65 |
| May-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 28.72 |
| Jun-20 | 0.02 | 0.02 | 0.26 | 0.26 | 0.00 | 0.00 | 0.00 | 0.00 | 36.62 |
| Sub-total | 11.96 | 11.96 | 0.95 | 0.95 | 0.00 | 0.00 | 0.00 | 0.00 | 151.77 |
| Jul-20 | 0.00 | 0.00 | 0.05 | 0.05 | 0.00 | 0.00 | 0.00 | 0.00 | 37.35 |
| Aug-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Sep-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Oct-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Nov-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Dec-20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Total | 11.96 | 11.96 | 1.00 | 1.00 | 0.00 | 0.00 | 0.00 | 0.00 | 189.12 |
| 2019 | 0.00 | 0.00 | 0.05 | 0.05 | 0.00 | 0.00 | 0.00 | 0.00 | 500.00 |
| Accumulated Total | 11.96 | 11.96 | 1.05 | 1.05 | 0.00 | 0.00 | 0.00 | 0.00 | 689.12 |

Appendix M
Statistics on Complaint, Notifications of
Summons and Successful Prosecutions

Statistical Summary of Exceedances

| Air Quality | | | | | | |
|---|---------------------|-------------|-------|--|--|--|
| Location | Action Level | Limit Level | Total | | | |
| E-A1 | 0 | 0 | 0 | | | |
| | N | oise | | | | |
| Location Action Level Limit Level Total | | | | | | |
| BEM Office | 1 | NA | 0 | | | |

Statistical Summary of Environmental Complaints

| Donarting Daried | Env | vironmental Complaint Statis | stics | |
|------------------|-----------|------------------------------|--------------------|--|
| Reporting Period | Frequency | Cumulative | Complaint Nature | |
| 1 Jul 2020- | 1 | 1 | Construction Noise | |
| 31 Jul 2020 | 1 | 1 | Construction Noise | |

Statistical Summary of Environmental Non-compliance


| Danarting Daried | Enviro | onmental Non-compliance St | atistics | |
|------------------|-----------|----------------------------|----------|--|
| Reporting Period | Frequency | Cumulative | Details | |
| 1 Jul 2020- | 0 | 0 | N/A | |
| 31 Jul 2020 | U | U | N/A | |

Statistical Summary of Environmental Summons

| Ī | Donarting Daried | En | vironmental Summons Statis | tics |
|---|----------------------------|-----------|----------------------------|------|
| | Reporting Period | Frequency | Details | |
| | 1 Jul 2020- 31 Jul 2020 | 0 | 0 | N/A |

Statistical Summary of Environmental Prosecution

| Donouting Dowload | Env | ironmental Prosecution Stati | stics |
|-------------------|-----------|------------------------------|-------|
| Reporting Period | Frequency | Details | |
| 1 Jul 2020- | 0 | 0 | NI/A |
| 31 Jul 2020 | 0 | 0 | N/A |



August 2020

| SUNDAY | MONDAY | TUESDAY | WEDNESDAY | THURSDAY | FRIDAY | SATURDAY |
|--------|---|---------------------------------|-----------|---|---|---|
| 26 | 27 | 28 | 29 | 30 | 31 | 1 |
| 2 | 3 | 4 Impact Dust monitoring (E-Al) | 5 | 6 | 7 | 8 |
| 9 | 10 Impact Dust monitoring (E-A1) | 11 | 12 | 13 | 14 | 15 Impact Dust monitoring (E-A1) |
| 16 | 17 | 18 | 19 | 20 | 21 Impact Dust monitoring (E-A1) | 22 |
| 23 | 24 | 25 | 26 | 27 Impact Dust monitoring (E-A1) | 28 | 29 |
| 30 | 31 | | | | | |

Appendix O
Interim Report for the Complaint

Interim Report on Environmental Complaint

| Project | Control Voyal on Doute Voi Tak Foot Section | | | | | |
|--------------------------------------|--|--|--|--|--|--|
| | Central Kowloon Route, Kai Tak East Section | | | | | |
| Complaint Code Complaint description | As notified by the Contractor on 22 Jul 2020, a complaint was logged on 1 Jul 2020 for | | | | | |
| | noise nuisance arising from the construction site at Kai Tak Area 1B, Site 4, Kai Tak, Kowloon. And the complaint was received by EPD on 3 Jul 2020. | | | | | |
| | "投訴人投訴於1/7在九龍啟德第1B區4號地盤受到噪音滋擾,要求環保署跟進及 | | | | | |
| | 回覆。" | | | | | |
| | The details of complaint was about noise arising from the construction works at the construction site around 8 am on the weekdays and also the restricted hours (including general holidays and night-time on the weekdays) which caused nuisance to the nearby residents. Also, the complainant urges the contractor to ensure the work fulfilling the environmental legislations and also conditions stipulated in the valid construction noise permit, and implement practicable measures to minimize the noise nuisance to the nearby residents. | | | | | |
| Parameter | Construction Noise | | | | | |
| Investigation finding | On 7 Jul 2020, EPD inspection was held to investigate the complaint about construction noise arising from manual handling which was the only construction works processing on 1 Jul 2020. The Contractor was told by EPD that manual handling in Kai Tak Area 1B, Site 4 has not violated the Noise Pollution Control Ordinance in designated area. | | | | | |
| | Further communications were made between EPD and the Contractor on 8 Jul 2020 regarding further information of the complaint. As noted from the Contractor, the complainant claimed that the noise nuisance was caused by handling of reinforcement mesh fabric and wood, however, the Contractor claimed that there was no PME being used on 1 Jul 2020. In addition, no observation regarding construction noise during weekly site inspection conducted on 8 Jul 2020. | | | | | |
| | Considering the fulfillment of stipulated requirements by the Contractor for CNP at the BEM office at the Kai Tak Area 1B (Permit No.: GW-RE0528-20), it is concluded that no non-compliance to the EM&A requirement of the Project regarding noise impact from construction works during restricted hours was observed. | | | | | |
| Actions taken / to be taken | Contractor is reminded to implement the below mitigation measures to minimize nuisance to the public. So, the followings are proposed: | | | | | |
| | Designation of site personnel for supervision on site work day-to-day. All the concreting work will be completed before 19:00. Handling of heavy duty material and noisy works will be restricted within the restricted hours. Lighting will provided at work site if necessary and avoid over bright or poorly directed lights onto neighboring properly. | | | | | |
| Remarks | See below for the complained working area | | | | | |
| Prepared by | Philip Chan | | | | | |
| Date | 30 Jul 2020 | | | | | |

