







Dissolved Oxygen (Bottom) at Mid-Ebb Tide






Works Contract HY/2014/07 – Central Kowloon Route – Kai Tak West

Graphical Presentation of Water Quality Monitoring Results




Dissolved Oxygen (Bottom) at Mid-Ebb Tide






Dissolved Oxygen (Bottom) at Mid-Flood Tide






Dissolved Oxygen (Bottom) at Mid-Flood Tide






Dissolved Oxygen (Surface & Middle) at Mid-Ebb Tide



Dissolved Oxygen (Surface & Middle) at Mid-EbbTide



Dissolved Oxygen (Surface & Middle) at Mid-Flood Tide



Dissolved Oxygen (Surface & Middle) at Mid-Flood Tide

