

Appendix J**Cumulative Statistics on Complaints, Notification of Summons and Successful Prosecutions**

	Date received	Subject	Status	Total no. received in this month	Total no. received since project commencement
Environmental complaints	14 June 2019 (Referred by the Contractor on 17 June 2019)	<p>Environmental Complaint No: EC-010-CKRKTW20190614_01_E065</p> <p><u>Details of Complaint:</u> A complaint was received by Gammon Construction Limited on 14 June 2019. The complaint was referred by the Contractor on 17 June 2019 regarding - Muddy plume observed outside the silt curtain of Central Kowloon Route – Kai Tak West, Kowloon on 14 June 2019.</p> <p><u>Details of Investigation and findings:</u> According to the Contractor information, construction works were only conducted within fully-enclosed silt curtain and the clutched pipe piling was conducted at inner side on 14 June 2019. It may be inferred that the muddy plume which observed outside the silt curtain could be caused by non-project related source.</p> <p>The regular site inspections were conducted by ET on 12 June 2019 and by ET and IEC on 19 June 2019, no muddy water discharge from site was observed during the site inspection and no muddy plume was observed outside the silt curtain even during the pipe piling. In addition, proper screening was also erected near the section of clutch pipe pile driving at inner side.</p> <p>It is considered that the proper mitigation measures for the marine works were implemented and provided by the Contractor. The potential source for the muddy plume was not caused from the project. To conclude, this complaint is considered to be not project related</p>	Closed	1	10
Notification of summons	--	--	--	0	0
Successful prosecutions	--	--	--	0	0