Appendix E

Cumulative Statistics on Exceedances, Complaints, Notifications of Summons and Successful Prosecutions

Table E-1 Environmental Complaints Log						
Complaint Log No.	Date of Complaint	Received From	Received By	Nature of Complaint	Investigation/Mitigation Action	Status
EC193_CKRCT20240424_782	24 th April	Letter	The	Flooding	The Management Office of Grand	Investigation
	2024		Contractor	caused by	Waterfront sent a letter to HyD/Kln	report was
	-		& Engineer	blockage of	Regional office to complain about	finalized on 7 th
			a Liighteer	drainage	the flooding caused by blockage of	June 2024.
				urunuge	drainage along San Ma Tau Street,	50110 202 11
					and requested for follow up action.	
					and requested for follow up detion.	
					According to the information	
					provided by the Contractor, a site	
					joint site inspection with relevant	
					government departments was held	
					on 26th April 2024. It was found that	
					part of the road drainage at No. 38	
					Sun Ma Tau Street was blocked. The	
					Contractor was arranged to clean	
					the blocked drains and channels to	
					reduce the risk of flooding.	
					Cleaning of blocked drains was	
					carried out between 30th April and	
					20th May 2024 by Contractor. After	
					the completion of cleaning work,	
					joint site inspection by the	
					Contractor, Drainage Services	
					Department and Highways	
					Department would be carried out	
					after the completion of cleaning	

Table E-1Environmental Complaints Log

Complaint Log No.	Date of Complaint	Received From	Received By	Nature of Complaint	Investigation/Mitigation Action	Status
					work.	
EC194_CKRCT2024502_784	2 nd May	1823	The	Flooding	1823 hotline referred a complaint on	Investigation
	2024		Contractor	caused by	2nd May 2024 to the Contractor	report was
			& Engineer	blockage of	about flooding caused by blockage	finalized on
				drainage	of drainage near San Ma Tau Street.	12 th June
					The complainant complained that	2024.
					flooding caused by blockage of	
					drainage was found on 20th April	
					2024. The complainant claimed that	
					dumping of concrete into the public	
					drainage had been observed long	
					time ago and requested for follow	
					up action.	
					According to the information	
					provided by the Contractor, a site	
					joint site inspection with relevant	
					government departments was held	
					on 26th April 2024. It was found that	
					part of the road drainage at No. 38	
					Sun Ma Tau Street was blocked. The	
					Contractor was arranged to clean	
					the blocked drains and channels	
					between 30 th April and 20 th May	
					2024 to reduce the risk of flooding.	
					Joint site inspection by the	
					Contractor, Drainage Services	

Complaint Log No.	Date of Complaint	Received From	Received By	Nature of Complaint	Investigation/Mitigation Action	Status
	Complaint	From	БУ	Complaint	Department (DSD) and Highways Department (HyD) was carried out after the completion of cleaning work on 5th June 2024. According to the Contractor, no comment from DSD or HyD has been received. The Contractor was suggested to arrange regular inspection for drainage system within the site and maintain good relations with the nearby sensitive receivers which	
					may be affected by the construction work such as providing better/ more detailed information about the work nature and informing in advance of the works to the nearby residents.	

Table E-2Cumulative Statistics on Complaints, Notifications of Summons and Successful Prosecutions and PublicEngagement Activities

Reporting Period	Complaints	Notifications of Summons and Prosecutions	Public Engagement Activities
This Month	1	0	0
Cumulative Project-to-Date	195	0	0

Table E-3 Cumulative Statistics on Monitoring Exceedance

Monitoring Parameter		No. of Exceedance		
	Month/Year	Action	Limit	
1-hour TSP	No. of Exceedance This Month	0	0	
	Cumulative Project-to-Date	0	0	
24-hour TSP	No. of Exceedance This Month	0	0	
	Cumulative Project-to-Date	0	0	
Noise	No. of Exceedance This Month	0	0	
(LAeq (30min))	Cumulative Project-to-Date	155	0	

Note:

No construction noise monitoring was conducted in the reporting month as the site had been handed over to Contract No. HY/2019/13 on 30 December 2023. Impact monitoring at M-A3/ M-N3 has been conducted by Environmental Team (HY/2019/13) since January 2024. The monitoring results at M-A3 and M-N3 are presented in the monthly EM&A Report prepared by Contract No. HY/2019/13.