




Copper (Depth-averaged) at Mid-Ebb Tide




Remarks: In accordance with Section 7.9 of the EM&A Manual, the detection limit for copper is 1.00µg/L.



Works Contract HY/2014/07 – Central Kowloon Route – Kai Tak West

Graphical Presentation of Water Quality Monitoring Results

Copper (Depth-averaged) at Mid-Ebb Tide




Remarks: In accordance with Section 7.9 of the EM&A Manual, the detection limit for copper is 1.00µg/L.



Works Contract HY/2014/07 – Central Kowloon Route – Kai Tak West

Graphical Presentation of Water Quality Monitoring Results

Copper (Depth-averaged) at Mid-Flood Tide




Remarks: In accordance with Section 7.9 of the EM&A Manual, the detection limit for copper is 1.00µg/L.



Works Contract HY/2014/07 – Central Kowloon Route – Kai Tak West

Graphical Presentation of Water Quality Monitoring Results

Copper (Depth-averaged) at Mid-Flood Tide



Remarks: In accordance with Section 7.9 of the EM&A Manual, the detection limit for copper is 1.00µg/L.



Works Contract HY/2014/07 – Central Kowloon Route – Kai Tak West

Graphical Presentation of Water Quality Monitoring Results