







## Suspended Solids (Depth-averaged) at Mid-Ebb Tide



Works Contract HY/2014/07 – Central Kowloon Route – Kai Tak West

Graphical Presentation of Water Quality Monitoring Results




## Suspended Solids (Depth-averaged) at Mid-Ebb Tide



Works Contract HY/2014/07 – Central Kowloon Route – Kai Tak West

Graphical Presentation of Water Quality Monitoring Results




## Suspended Solids (Depth-averaged) at Mid-Flood Tide



Works Contract HY/2014/07 – Central Kowloon Route – Kai Tak West

Graphical Presentation of Water Quality Monitoring Results

## Suspended Solids (Depth-averaged) at Mid-Flood Tide



Works Contract HY/2014/07 – Central Kowloon Route – Kai Tak West

Graphical Presentation of Water Quality Monitoring Results